



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2231X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER -RH (WCP)	DENTED	1,446.30	270.00
1	FRONT BUMPER (WCP)	CUT	663.90	220.00
10	FRONT BUMPER CLIPS @\$5.50 (WCP)	NECESSARY	55.00	15.00
2	FRONT BUMPER SIDE HOLDER -LH/RH @\$115.20 (WCP)	O/S NECESSARY	230.40	40.00
1	FRONT BUMPER LOWER GARNISH, BLACK (WCP)	SCRATCHED	314.20	110.00
1	HEAD LAMP - RH (WCP)	SCRATCHED	3,560.70	900.00
1	HEAD LAMP LOWER RETAINER - RH (WCP)	NOT NECESSARY	62.10	-
1	FRONT FENDER COWLING - RH (WCP)	DEFORMED	522.50	160.00
1	SET FRONT FENDER COWLING CLIPS -LH (10PCS) (WCP)	NECESSARY	24.70	15.00
1	FRONT FENDER INNER PANEL -RH (WCP)	NOT NECESSARY	99.40	-
1	FRONT RIM - RH (WCP)	NOT NECESSARY	2,764.20	-
1	REAR BUMPER (WCP)	CUT	1,540.10	500.00
1	REAR BUMPER CLIPS (WCP)	NECESSARY	15.00	15.00
2	REAR BUMPER SIDE HOLDER -LH/RH @\$82.70 (WCP)	N/S NECESSARY	165.40	50.00
1	REAR BUMPER LOWER GARNISH , BLACK (WCP)	SCRATCHED	448.30	150.00
1	R/FR SHOCK ABSORBER (WCP) (ADDITIONAL)	BENT	170.00	170.00
1	R/R OUT BUMPER BRKT (WCP) (ADDITIONAL)	DISTORTED	40.00	40.00
	COST PLUS 10%		1,212.22	265.50
			13,334.42	2,920.50
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER SENSOR (SN)	SERVICEABLE	220.00	-
			220.00	-
<u>LABOUR</u>				
	TO KNOCK OUT DENTS, RHR FENDER, REMOVE, REPLACE ACCIDENT PARTS.		666.00	666.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,000.00	700.91
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO RESET CHECK LIGHT.	NOT NECESSARY	70.00	-
	TO TUFF-KOTE.	NOT NECESSARY	60.00	-
	TO REMOVE, REPLACE RHF TYRE RIM AND BALANCING TYRE.	NOT NECESSARY	45.00	-

Report Ref No. CS/SPF22006305/Vcy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO 4 WHEEL ALIGNMENT.		70.00	60.00
	ADJUST CASTER ANGLE (ADDITIONAL).		120.00	120.00
			2,081.00	1,546.91
GRAND TOTAL			15,635.42	4,467.41
RECOMMENDED COST OF REPAIRS				4,467.41

Report Ref No. CS/SPF22006305/Vcy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,400-\$5,000

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.