



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22006305/Vcy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)		Date:	22/06/2023
POLICE LOGISTICS BASE (PLB)			
1 HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 761J	Veh. Inspected	SKU 2231X
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/040	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	01/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HARRIER 2.0	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600046321	Colour	BLACK
Odometer	78920 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT & O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	28/06/2022	Inspection Date	07/07/2022
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	