# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

# **VEHICLE INSPECTION REPORT**

Report No.: PAS/TP/0160522

Date of Report

: 26/05/2022

To: Ms Lim De Min

C/o. 25, Kaki Bukit Road 4,

Synergy@KB, #06-53. Singapore 417800

Date of Assignment Report requested by

: 17/05/2022 : Ms Lim De Min

Date of Accident

: 18/04/2022

Date of Inspection

: 17/05/2022

Claim No.

: Third Party Claim

Policy No.

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SKT318Z

Engine Capacity (cc) : 1984cc

Make & Model

: Audi Q5 Sport 2.0 TFSI Quattro S Tror Mileage (km)

: 73911km

Date of Registration

: 08/07/2019

Chassis / Frame No.

: WAUZZZFY0K2091743

Colour

: Met. Blue

Engine No.

: DAX056237

### **TYRE CONDITION**

Front LH

: 6 mm

Front RH

: 6 mm

Make

: Michelin

Make

: Michelin

Rear LH

: 6 mm

Rear RH

: 6 mm

Make

: Michelin

Make

: Michelin

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Glockewerke

25, Kaki Bukit Road 4, Synergy@KB, #06-53, Singapore 417800

# ASSESSMENT

Repairer's Estimate

Recommended Reserve

11,058.00 : \$

Revised Amount

: \$ 8,828.10

Less Excess

: \$ \$

8,828.10 (Part-By-Part)

Estimated Normal Period of Repairs

: 5 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SKT318Z

**Report No. : PAS/TP/0160522** 

# **GENERAL REMARKS**

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Glockewerke, 25, Kaki Bukit Road 4, Synergy@KB, #06-53, Singapore 417800.

### POINT OF IMPACT / ACCIDENT SCENE PHOTOGRAPHS

The vehicle sustained Left Hand Front portion damages during the accident on 18/04/2022. The Left Hand Front roadwheel was also affected.

It was report that the vehicle has been parked and subsequently hit by a lorry while reversing.

From the evidence of 9 pieces accident scene photographs and 4 pieces photos of video footage captured from the vehicle SKT318Z dashcam (*provided by the owner*), damages appeared consistent with the Police Report made.











# PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com


Business Reg. 201404434D

Vehicle No: SKT318Z

Report No.: PAS/TP/0160522

## **ACCIDENT SCENE PHOTOGRAPHS**











### POINT OF IMPACT / VIDEO FOOTAGE CAPTURED FROM VEHICLE SKT318Z





Footage Captured No.1



Footage Captured No.2



Footage Captured No.3

Footage Captured No.4

P<sub>AS</sub>

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address; My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SKT318Z

**Report No.: PAS/TP/0160522** 

#### DAMAGES / DAMAGED PARTS RECOMMENDATION

The bonnet, LHF fender, LHF fender top fledge cover and LHF aluminium rim were Dented / Distorted / Defaced.

Other parts were also found damaged. (See schedule for details)

Note: The bonnet and LHF wheel rim were made by aluminium material. Aluminium is unlike metal steel in that it doesn't have a "Memory Metal". It cannot be reshaped back to its undamaged state as easily as steel even though trying to perform welding and panel beating. Especially the surface are badly Dented/Distorted and/or brushed chrome surface was Defaced. Therefore, we recommended to be replace.

### PART-BY-PART / LUMP SUM REPAIRS RECOMMENDATION

The used parts for this model were not available. Beside, the vehicle is only about 2 years and 10 months old. And it is still under warranty by Agent of Premium Automobiles. In our opinion, it is fair and reasonable for Part-by-Part Repairs Basis to reinstate/revert the vehicle back to its road-worthy / pre-accident condition.

### ADJUSTMENT RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$8,828.10.

### CONCLUSION

The repairer has agreed to undertake repairs at our adjusted amount of SGD \$8,828.10 corresponding to labour charges, spray painting and replacement of parts.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

Note: The vehicle has yet to be repaired. Resurvey "Before Painting" on new parts and 'After Repairs" will be conducted thereafter when vehicle is ready to send in for repair.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

**Prominent Appraiser Services Pte Ltd** 

Andrew How

**Automobile Appraiser** 

**MSAAA** 

Licensed Appraiser



Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Repairer's

Vehicle No: SKT318Z

Report No.: PAS/TP/0160522

Our

# APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Estimate (S\$)		Assessment (S\$)	
1	1 pc	Bonnet (Aluminium)	Dented/Distorted	\$	4,280.00	\$	4,280.00	
2	1 pc	Bonnet stay absorber LH	Refit	\$	128.00	\$	-	
3	1 pc	Frt fender LH	Dented	\$	1,462.00	\$	1,462.00	
4	1 pc	Frt fender emblem (S-Line) LH	Necessary	\$	133.00	\$	133.00	
5	1 pc	Frt fender wheel arch protector LH	Refit	\$	709.00	\$	-	
6	1 pc	Frt fender top fledge cover LH	Dented/Distorted	\$	87.00	\$	87.00	
7	1 pc	Frt fender wheel liner LH	Refit	\$	303.00	\$	H	
8	1 pc	Frt wheel rim (Aluminium) LH	Dented/Defaced	\$	2,036.00	\$	2,036.00	
9	1 pc	Frt fender inner panel LH	Dented/Repair		(Ref	fer labour	no. 4 & 5)	
				\$	9,138.00	\$	7,998.00	
			Less Discount:			5% \$	399.90	
			List Parts Sub-Total:	\$	9,138.00	\$	7,598.10	
			Parts Total :	\$	9,138.00	\$	7,598.10	
S/No.	o. Labour Descriptions			Repairer's Estimate (S\$)		Our Assessment (S\$)		
		ove and reinstall affected electrical w ck affected electrical wiring system.	iring system for necessary repairs.	\$	50.00	\$	30.00	
	10 chec	ck affected electrical withing system.		Ψ	30.00	Ψ	30.00	
2	To replace/install LHF tyre and rim and to perform wheel balancing.				20.00	\$	20.00	
3	To conduct front wheel alignment.				100.00	\$	80.00	
4	To straighten, repair, realign on affected area and replace damaged parts.			\$	750.00	\$	500.00	
5	To spray painting, blending on affected and adjacent area.			\$	1,000.00	\$	600.00	
			Labour Total:	\$	1,920.00	\$	1,230.00	
			Total (Parts & Labour) :	\$	11,058.00	\$	8,828.10	

### For Repairs Part By Part Amount

The final adjusted Part-By-Part amount is: 8,828.10

Under normal circumstances, the repairs should be completed within a reasonable period

Working Days. (Exclude Sunday, Pubic Holiday and awaiting of shipment for spare parts)

28 Photographs were taken at the time of inspection.









