

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006313/KPA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220015406
Claimant Vehicle No :	SMX9816Z	Insured Vehicle No :	GBL1397L
Date of Loss:	28/06/2022	Nature of Claim:	TP
		Claim No:	9689991913SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX9816Z	Engine No:	L15B5577478
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11327441
Reg. Date:	08/02/2021 (Man. Year: 2019)	Odometer:	24275 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,922.70	816.08	4,106.62	83.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	855.00	1,235.00	59.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	7,012.70	1,671.08	5,341.62	76.17
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	30/06/2022	
Date Inspected:	30/06/2022 Inspected At:	Jin Huat & Co (HQ) 176 SIN MING DRIVE #05-01, SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,552.60 F	*- FL
2	1		*TAILGATE EMBLEM LOGO	Not Necessary	75.60 F	*- FL
3	1		*RH T/LAMP	Serviceable	540.15 F	*- FL
4	1		*REAR BODY PANEL	Repair	972.15 F	*- FL
5	1		*REAR BUMPER SIDE RETAINER	Distorted	68.00 F	*68.00 FL
6	1		*REAR BUMPER	Dented / Cut	553.10 F	*553.10 FL
7	1		*REAR BUMPER REFLECTOR	Serviceable	38.00 F	*- FL
8	1		*RH BUMPER SIDE GARNISH	Buckled / Distorted	182.00 F	*182.00 FL
9	1		*RH T/GATE REFLECTOR	Serviceable	320.80 F	*- FL
10	1		*RH WHEEL ARCH COVERING	Distorted	289.00 F	*189.00 FL
11	10		*CLIPS	Necessary	28.00 F	*28.00 FL
12	1		*REAR WINDSCREEN MOULDING TOP	Not Necessary	86.50 F	*- FL
13	1		*REAR WINDSCREEN MOULDING LOWER	Not Necessary	86.50 F	*- FL
14	1		*REAR WINDSCREEN MOULDING R/H	Not Necessary	65.15 F	*- FL
15	1		*REAR WINDSCREEN MOULDING L/H	Not Necessary	65.15 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,922.70	1,020.10
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	204.02
Total Parts (\$)	4,922.70	816.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DISMANTLE ,REPAIR OR REPLACE DAMAGED PARTS WHERE NECESSARY	New	950.00	360.00
2	TO REMOVE /REFIT REAR WINDSCREEN	New	180.00	0.00
3	SPRAY PAINTING	New	900.00	480.00
4	TO CHECK WIRING FUNCTIONS	New	60.00	15.00
			Gross Labour Cost (\$\$)	2,090.00
				855.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >