

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22006314/APA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210153479
<b>Claimant Vehicle No :</b>	SNC5253Y	<b>Insured Vehicle No :</b>	SND3152M
Date of Loss:	26/06/2022	Nature of Claim:	TP
		Claim No:	1765131841SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNC5253Y</b>		
Make & Model:	HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A)	Engine No:	G4FMMU073702
Reg. Date:	27/10/2021 (Man. Year: 2021)	Chassis No:	KMHLN41ETNU238081
Colour:	White	Odometer:	44082 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,967.90	1,754.48	1,213.42	40.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	860.00	340.00	28.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,167.90</b>	<b>2,614.48</b>	<b>1,553.42</b>	<b>37.27</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,167.90</b>	<b>2,100.00</b>	<b>2,067.90</b>	<b>49.61</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>Nett Liability (S\$)</b>		<b>2,280.00</b>		

**INSPECTION**

Date of Assignment:	30/06/2022	Advance Auto Garage (HQ) 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE Singapore 415933
Date Inspected:	30/06/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,993.10 F	*1,993.10 FL
2	1		*REAR RH DOOR LOCK	Not Necessary	495.40 F	*- FL
3	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	249.40 F	*- FL
4	1		*REAR RH DOOR SURROUND FELT	Cut	150.00 FS	*80.00 FS
5	1		*REAR RH DOOR BLACK TAPE	Necessary	80.00 FS	*80.00 FS
					<b>Sub Total (\$\$)</b>	<b>2,967.90</b>
					<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>
					<b>Total Parts (\$\$)</b>	<b>2,967.90</b>

2,153.10  
398.62  
1,754.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	100.00	50.00
5	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,200.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >