

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006319/EVY3Q2**Date:** 14/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00197932100

Claimant Vehicle No : SLP8969B **Insured Vehicle No :** SKF9188X

Date of Loss: 28/06/2022 Nature of Claim: TP Claim No: SNM22D204555/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP8969B**

Make & Model: MAZDA 3, 1.5 SEDAN (A) Engine No: P520444337

Reg. Date: 21/06/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0152698

Colour: Blue Odometer: 288895 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15

Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	925.00	895.00	30.00	3.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	656.27	556.27	100.00	15.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,581.27	1,451.27	130.00	8.22
Approved Total (Overridden) (\$\$)		1,161.02		
(\$\$)	1,581.27	1,161.02	420.25	26.58
+ GST 7.00/7.00% (\$\$)	110.69	81.27	29.42	26.58
Nett Amount (\$\$)	1,691.96	1,242.29	449.67	26.58

INSPECTION

Date of Assignment: 01/07/2022

Date Inspected: 05/07/2022 Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck)
74 Kian Teck Road
Singapore 628800

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
Parts:	143	MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8969B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/R DOOR	Dented	1,250.00 FL	*1,250.00 FL
2	1		*L/R OUTER D/FOIL UPP (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*L/R OUT DOOR RR FOIL (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*L/R OUT DR FRT FOIL (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*MISCELLANEOUS (10) DOOR TRIM CLIP	Necessary	50.00 FS	*20.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					1,300.00	1,270.00
- List Item Discount on L Items 30.00/30.00% (S\$)					375.00	375.00
Total Parts (S\$)					925.00	895.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	55.0 WU X 50.00 SGD/H	New	275.00	175.00
2	LABOUR COST 59.0 WU X 50.00 SGD /H	New	295.00	295.00
3	MATERIAL COST	New	86.27	86.27
Gross Labour Cost (S\$)			656.27	556.27

Report was unsubmitted during this print-out.

< END OF ESTIMATES >