

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22006329/VCY3M4**Date:** 08/09/2022**REFERENCE**

Insured/Claimant:	WONG KIA LIM WILLY	Policy No:	SP2001787351	
Date of Loss:	30/06/2022	Nature of Claim:	OD	Claim No: 202222005453

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF6234R		
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A)	Engine No:	CAV293175
Reg. Date:	26/07/2011 (Man. Year: 2011)	Chassis No:	WVWZZZ16ZBM101174
Colour:	Multi-colour	Odometer:	0 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,470.50	1,996.50	1,474.00	42.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	850.00	120.00	12.37
Paintwork Labour	1,200.00	1,000.00	200.00	16.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,640.50	3,846.50	1,794.00	31.81
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,040.50	3,246.50	1,794.00	35.59
+ GST 7.00/7.00% (S\$)	352.84	227.26	125.58	35.59
Nett Amount (S\$)	5,393.34	3,473.76	1,919.58	35.59

INSPECTION

Date of Assignment:	03/07/2022	Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	06/07/2022	Inspected At:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12 Singapore 539147
Estimated Period of Repair:	6.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2022)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI 1623Q5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF6234R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH (WCP)	Dented	230.00 F	*300.00 F
2	1		*FRONT FENDER VERTICAL GARNISH LH (WCP)	Dented	85.00 F	*20.00 F
3	10		*FRONT FENDER SHIELD CLIP (WCP)	Not Necessary	55.00 F	*- F
4	1		*FRONT DOOR LH (WCP)	Dented	850.00 F	*850.00 F
5	1		*FRONT DOOR HINGE TOP LH (WCP)	Shifted	45.00 F	*55.00 F
6	1		*FRONT DOOR HINGE LOWER LH (WCP)	Shifted	65.00 F	*55.00 F
7	1		*FRONT DOOR CHECKER LH (WCP)	Not Necessary	55.00 F	*- F
8	1		*FRONT DOOR TOP MOULDING LH FRONT DOOR SEAL OUTER LH INSTEAD OF TOP MOULDING LH (WCP)	Necessary	110.00 F	*90.00 F
9	1		*FRONT DOOR OUTER MOULDING LH (WCP)	Necessary	65.00 F	*60.00 F
10	1		*FRONT DOOR OUTER HANDLE LH (WCP)	Not Necessary	100.00 F	*- F
11	1		*FRONT DOOR SIDE MIRROR LH (WCP)	Cracked	140.00 F	*220.00 F
12	1		*FRONT DOOR SIDE MIRROR COVER LH (WCP)	Cracked	65.00 F	*90.00 F
13	1		*REAR DOOR LH (WCP)	Repair	980.00 F	*- F
14	1		*REAR DOOR OUTER MOULDING LH (WCP)	Necessary	100.00 F	*75.00 F
15	1		*REAR DOOR RUBBER LH (WCP)	Serviceable	85.00 F	*- F
16	1		*CENTRE PILLAR GARNISH LH (WCP)	Serviceable	125.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	3,155.00	1,815.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	315.50	181.50
Total Parts (\$\$)	3,470.50	1,996.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	1,200.00	1,000.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	100.00	30.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	820.00	800.00
Gross Labour Cost (\$\$)			2,170.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >