

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0254/22

DATE : 02-JUL-2022

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD

#17-00 TOWER BLOCK

MND COMPLEX S(069110)

TEL : 62239433

FAX : 62234190

ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS CINDY GOH

ADDRESS : 132 MIMOSA CRESCENT

S(808075)

TELEPHONE NO : 96312664

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 7210015438

VEHICLE NO : SMX6746L

MODEL CODE : FDWARV9P15HDA-D---

MODEL/YEAR : KICKS 1.2L E-POWER PREMIUM PLUS

ENGINE NO : HR12361274C

CHASSIS NO : MNTFEAP15Z0000877

MILEAGE : 45932 KM

DATE IN : 02/07/2022

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 01/07/2022

-9045 0084 elmu@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMX6746L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR & BOTH RR FNDR RENEW REAR END PANEL,HATCHBACK DOOR & RR BUMPER	2340.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1800.00	
3	ZZ/003	APPLY SEALANT TO REAR END PANEL AND HATCHBACK DOOR	200.00	
4	ZZ/004	REMOVE AND INSTALL REAR WINDSCREEN GLASS	220.00	
5	ZZ/005	REMOVE AND INSTALL REVERSE CAMERA	150.00	
6	ZZ/006	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	120.00	
7	ZZ/007	RENEW REVERSE SENSOR	150.00	
8	ZZ/008	RENEW LH RR COMB LAMP & HATCHBACK DOOR LAMP CHECK & INSPECT RH RR COMB LAMP REPLACE IF DAMAGE	88.00	
9	ZZ/009	SUPPLY REAR LICENSE PLATE		
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	180.00	
11	ZZ/10	PERFORM RUSFT PROOFING TREATMENT TO TRUNK FLOOR AND REAR END PANEL \$120.00 PER PANEL	240.00	
		TOTAL LABOUR CHARGES	5488.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX6746L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
1	LH RR FENDER WHEEL ARC MOULDING	93829-5RF0A	407.20		
2	WEATHER STRIP HATCHBACK DOOR	90830-5RY0A	75.80		
3	CLIP RR BUMPER @SGD\$ 15.40 EACH	01553-1HA0A	30.80		
4	RH REFLECTOR RR BUMPER	26565-8990B	66.90		
5	LH REFLECTOR RR BUMPER	26560-8990B	66.90		
6	RH RR HATCHBACK DOOR LAMP	26550-5RY0B	246.60		
7	RH RR COMB LAMP	26550-5RY0A	867.80		
8	LH RR HATCHBACK DOOR LAMP	26555-5RY0B	246.60		
9	LH RR COMB LAMP	26555-5RY0A	867.80		
10	REVERSE SENSOR @SGD\$250.40 EACH	28438-4CL0B			1001.60
11	REVERSE SENSOR COVER BRACKET @SGD\$31.30 EACH	28533-6CA0C			125.20
12	REAR LICENCE PLATE	RLP			60.00
13	SUNDRIES	NPN			50.00
14	EMBLEM - PREMIUM PLUS	84890-PREMIUM			40.00
15	REAR W/SCREEN SEALANT	SEALANT - 4			80.00
16	EMBLEM-BACK DOOR E POWER	90893-5RY0A	127.10		
17	ORNAMENT-BACK DOOR KICK	90892-5RB0A	70.00		
18	HATCHBACK DOOR	K010M-5RYMA	673.90		
19	HATCHBACK DOOR LOCK	90331-00Q0B	126.50		
20	RH SIDE BRACKET RR BUMPER	85220-5RF0A	70.20		
21	LH SIDE BRACKET RR BUMPER	85221-5RF0A	70.20		
22	STAY-RR BUMPER @SGD\$107.70 EACH	H5212-1HJMA	209.40		
23	ENERGY ASBORBER RR BUMPER	85090-5RY0A	84.70		
24	CROMMET-SCREW RR BUMPER @ SGD\$2.90 EACH	63846-5V000	11.60		
25	REAR BUMPER	85022-5RJ0H	591.60		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMX6746L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
26	RH RR FENDER INNER TRIM FINISHER	84950-5RY0A	96.00		
27	LH RR FENDER INNER TRIM FINISHER	84951-5RY0A	96.00		
28	CARPET-LUGGAGE TRUNKFLOOR	84904-5RY0A	314.50		
29	BOX-LUGGAGE TRUNKFLOOR	84975-5RY0A	268.40		
30	PLATE LUGGAGE REAR GARNISH	84992-5RY0A	90.40		
31	REAR END PANEL	G9100-5RYAA	407.50		
SUB TOTAL			6184.40	0.00	1356.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1236.88	0.00	0.00
GRAND TOTAL			4947.52	0.00	1356.80
OVERALL TOTAL			6304.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMX6746L

TOTAL LABOUR CHARGES	5488.00
TOTAL SPARE PARTS CHARGES	6304.32

GRAND TOTAL	11792.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.