

ASS.

ASS. REC. BY:

REF:

LPCI 22006335/KC

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

26 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Firm's

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$)

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

04/07/2022

Owner: U&G CAR LEASING


ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SML7522Y

1pc	rear tailgate
2pcs	raer tailgate hinge @\$178.10
1pc	rear tailgate "HYBRID" emblem
1pc	rear tailgate windscreen glass
1pc	rear tailgate windscreen moulding
1pc	rear tailgate outer chrome
1pc	rear tailgate "TOYOTA" logo
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
2pcs	rear tailgate inner side garnish @\$289.90
1pc	rear tailgate inner handle garnish
2pcs	rear taillamp @\$781.55
2pcs	rear taillamp lower garnish @\$371.85
2pcs	rear taillamp lower garnish side retainer @\$172.25
1pc	rear bumper
2pcs	rear bumper side retainer @\$172.10
1pc	rear bumper LH side reflector
1pc	rear bumper towing cover
10pcs	rear bumper clip @\$5.00
1pc	rear end panel
1pc	rear end panel inner garnish
1pc	rear end panel outer sensor 1
1pc	rear end panel outer sensor 2
1pc	rear end panel outer hardness
1pc	rear floor panel
1pc	rear floor panel inner tirm
1pc	rear floor panel top board tirm

less 25%
balance c/f

B1	\$	1,712.85	✓
	\$	356.20	X
Mr	\$	132.25	—
Mr	\$	1,417.85	X
Mr	\$	181.80	✓
Mr	\$	581.90	X
Mr	\$	121.10	X
Mr	\$	581.90	✓
Dis/Ret	\$	371.85	50% in
Mr	\$	371.75	✓
	\$	579.80	?
Mr	\$	121.10	✓
Mr	\$	1,563.10	X
M/S	\$	743.70	
M/S Dis	\$	344.50	4+
Mr	\$	1,217.45	✓
M/S Dis	\$	344.20	4+
Mr	\$	181.90	X
	\$	43.50	✓
Mr	\$	50.00	✓
B1	\$	781.10	✓
M/S	\$	378.85	✓
	\$	381.50	?
	\$	381.50	?
	\$	1,217.10	?
Mr	\$	972.10	X
Return	\$	581.90	✓
CM	\$	1,238.00	✓

\$ 16,950.75
\$ 4,237.69
\$ 12,713.06



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

04/07/2022

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SML7522Y

balance b/f

\$ 12,713.06

1 set	rear parking sensor	CM	s.nett	\$	280.00	200.00
1pc	rear bumper chrome	Bu	s.nett	\$	180.00	✓
1pc	rear end panel inner garnish chrome sealant	Bu	s.nett	\$	180.00	✓
		M	s.nett	\$	120.00	40.00
	remove & refit rear cushion			\$	280.00	80.00
	remove & refit rear windscreen glass			\$	120.00	✓
	wiring			\$	150.00	20.00
	tuffkote			\$	150.00	60.00
	spray painting			\$	1,400.00	700.00
	labour charges			\$	1,400.00	80.00
	Total			\$	16,973.06	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

