

ASS. REC. BY:

REF:

LPCI 22006335/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM 75224 Yr Regn: 03, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Noah c.c. 1797Colour: h. Black A/C: Insured / Std / NI / NASp. Reading: 216999 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR80 0377131Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F. Goform 195 / 65R15R: PailunBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 9 mmL/Bal. 8 mm L/Bal. 9 mmD.O.A. 4/7/22 D.O.I. 4/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ GIA not ready

8/8 11PM & 6900h Canhu 12/8/22

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Lompex
Vch In.


Tel: 64515752 (2 Lines) . Fax: 64514658

Not Noted
L1 Page 8 6900p
Heavy After Rain
6 days

Owner: U&G CAR LEASING

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1pc	rear tailgate	1712.85	1,712.85	
2pcs	rear tailgate hinge @\$178.10	356.20	356.20	
1pc	rear tailgate "HYBRID" emblem	132.25	132.25	
1pc	rear tailgate windscreen glass	1,417.85	1,417.85	
1pc	rear tailgate windscreen moulding	181.80	181.80	
1pc	rear tailgate outer chrome	581.90	581.90	
1pc	rear tailgate "TOYOTA" logo	121.10	121.10	
1pc	rear tailgate inner lock	581.90	581.90	
1pc	rear tailgate inner rubber	371.85	371.85	
1pc	rear tailgate inner garnish	371.75	371.75	
2pcs	rear tailgate inner side garnish @\$289.90	579.80	579.80	
1pc	rear tailgate inner handle garnish	121.10	121.10	
2pcs	rear taillamp @\$781.55	1,563.10	1,563.10	
2pcs	rear taillamp lower garnish @\$371.85	743.70	743.70	
2pcs	rear taillamp lower garnish side retainer @\$172.25	344.50	344.50	
1pc	rear bumper	1,217.45	1,217.45	
2pcs	rear bumper side retainer @\$172.10	344.20	344.20	
1pc	rear bumper LH side reflector	181.90	181.90	
1pc	rear bumper towing cover	43.50	43.50	
10pcs	rear bumper clip @\$5.00	50.00	50.00	
1pc	rear end panel	781.10	781.10	
1pc	rear end panel inner garnish	378.85	378.85	
1pc	rear end panel outer sensor 1	381.50	381.50	
1pc	rear end panel outer sensor 2	381.50	381.50	
1pc	rear end panel outer hardness	1,217.10	1,217.10	
1pc	rear floor panel	972.10	972.10	
1pc	rear floor panel inner trim	581.90	581.90	
1pc	rear floor panel top board	1,238.00	1,238.00	

\$ 16,950.75
\$ 4,237.69
\$ 12,713.06



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

04/07/2022

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SML7522Y

balance b/f \$ 12,713.06

1set	rear parking sensor	CM s.nett	\$ 280.00	200.00
1pc	rear bumper chrome	Bu s.nett	\$ 180.00	✓
1pc	rear end panel inner garnish chrome	Bu s.nett	\$ 180.00	✓
	sealant	M s.nett	\$ 120.00	40.00
	remove & refit rear cushion		\$ 280.00	80.00
	remove & refit rear windscreen glass		\$ 120.00	✓
	wiring		\$ 150.00	20.00
	tuffkote		\$ 150.00	60.00
	spray painting		\$ 1,400.00	700.00
	labour charges		\$ 1,400.00	800.00
	Total		\$ 16,973.06	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

04/07/2022

Owner: U&G CAR LEASING

SUPPLEMENTARY TO REPAIR TOYOTA NOAH 1.8X - SML7522Y

1pc	rear end panel LH side panel	301.60	B1 \$	385.20	✓
1pc	rear LH fender inner garnish		ngent \$	680.50	✓
			\$	1,065.70	
	less 25%		\$	266.43	
			\$	799.28	

