

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006336/UPA3Q2**Date:** 30/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070118338
Claimant Vehicle No :	SLR6686U	Insured Vehicle No :	SLB2777B
Date of Loss:	02/07/2022	Nature of Claim:	TP
		Claim No:	4736912640SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR6686U	Engine No:	BPJ144081
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4F29N046961
Reg. Date:	20/05/2009 (Man. Year: 2009)	Odometer:	254926 km
Colour:	Silver		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,483.20	8,298.53	6,184.67	42.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,360.00	940.00	40.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,783.20	9,658.53	7,124.67	42.45
Approved Total (Overridden) (S\$)		7,700.00		
(S\$)	16,783.20	7,700.00	9,083.20	54.12
+ GST 7.00/7.00% (S\$)	1,174.82	539.00	635.82	54.12
Nett Amount (S\$)	17,958.02	8,239.00	9,719.02	54.12
+ Car Rental (5.0 x S\$140.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,990.00		
Global Sum Settlement (S\$)		8,950.00		

INSPECTION

Date of Assignment:	04/07/2022	
Date Inspected:	04/07/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Badly Dented	2,700.00 FL	*2,662.30 FL
2	1		*BOOT LID LOGO EMBLEM	Necessary	260.00 FL	*100.85 FL
3	1		*BOOT LID A6 EMBLEM	Necessary	250.00 FL	*88.20 FL
4	1		*BOOT LID 2.0T EMBLEM	Necessary	230.00 FL	*80.00 FL
5	1		*BOOT LID WEATHERSTRIP	Twisted	499.00 FL	*285.00 FL
6	1		*REAR BUMPER	Deformed	2,399.00 FL	*2,005.00 FL
7	2		*REAR BUMPER SIDE RETAINER	Not Necessary	200.00 FL	*- FL
8	1		*REAR BUMPER BRACKET	N/S Cracked	250.00 FL	*125.00 FL
9	1		*REAR BUMPER CHROME	Cracked	388.00 FL	*292.00 FL
10	1		*REAR BUMPER LOWER GARNISH	Twisted	488.00 FL	*345.21 FL
11	1		*REAR BUMPER SPONGE	No such part	299.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Repair	800.00 FL	*- FL
13	1		*REAR BUMPER CENTRE BRACKET	Cracked	399.00 FL	*322.00 FL
14	4		*REVERSE SENSOR	Shorted (2 PCS ONLY)	1,080.00 FL	*410.00 FL
15	4		*REVERSE SENSOR BRACKET	Necessary	240.00 FL	*100.00 FL
16	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	500.00 FL	*- FL
17	1		*BOOT LID LAMP	N/S Cracked	1,774.00 FL	*805.00 FL
18	1		*TAILLAMP	N/S Cracked	1,800.00 FL	*820.00 FL
19	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*40.00 FS
20	1		*REAR NUMBER PLATE (THAILAND)	Necessary	250.00 FS	*80.00 FS
21	1		*BOOT LID SEALANT	Necessary	120.00 FS	*50.00 FS
22	12		*BOOT LID INSULATOR CLIP	Not Necessary	60.00 FS	*- FS
23	1		*REAR BUMPER CLIP (12 PCS)	Necessary	60.00 FS	*50.00 FS
24	12		*REAR BUMPER RIVET	Necessary	60.00 FS	*60.00 FS
25	12		*REAR BUMPER LOWER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,211.00	8,720.56
- List Item Discount on L Items 5.00/5.00% (\$\$)	727.80	422.03
Total Parts (\$\$)	14,483.20	8,298.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT SYSTEM AND WIRING	New	50.00	20.00
2	INSTALL REVERSE SENSOR	New	150.00	50.00
3	TRANSFER BOOT LID PARTS	New	150.00	60.00
4	APPLY BODY SEALANT TO CAR JOINTS	New	150.00	0.00
5	RE-SPRAY ANTI-RUST	New	150.00	30.00
6	TO RECALIBRATE REVERSE SENSOR USING DIAGNOSTIC SCANNER	New	250.00	100.00
7	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL,REPAIR INNER PANEL ,REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	700.00	500.00
8	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	700.00	600.00
Gross Labour Cost (\$)			2,300.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >