

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22006337/KPA3Q2**Date:** 02/02/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : FBN6265R **Insured Vehicle No :** SMK6724T

Date of Loss: 29/06/2022 Nature of Claim: TP Claim No: MFL2022D0003480

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN6265R**
 Make & Model: HONDA CB400SF, 399cc Engine No: NC42E1401166
 Reg. Date: 19/11/2018 (Man. Year: 2018) Chassis No: NC421901162
 Colour: Blue Odometer: 68359 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 R17 Rear Tyre Size: 160/60 R17
 Front Left Side: Bridgestone 3 mm Rear Left Side: Bridgestone 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,158.50	4,429.70	2,728.80	38.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	470.00	185.00	285.00	60.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,628.50	4,614.70	3,013.80	39.51
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	7,628.50	3,700.00	3,928.50	51.50
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
Nett Liability (S\$)		3,760.00		

INSPECTION

Date of Assignment: 04/07/2022

Date Inspected: 04/07/2022 Inspected At:

Sg 98 Motor Pte Ltd (HQ)
 BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
 #01-21
 Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Oct 2022)	
Parts:	N/A	HONDA CB400SF 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN6265R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUDGUARD	Buckled	280.00 FL	*245.00 FL
2	1		*TAIL PANEL	Repair	230.00 FL	*- FL
3	1		*EXHAUST PIPE	Bent	1,500.00 FL	*1,240.00 FL
4	1		*REAR BOX GIVI	Dented / Cut	350.00 FL	*245.00 FL
5	1		*SIDE BOX RH	Cracked	280.00 FL	*280.00 FL
6	1		*SIDE BOX LH	Cracked	280.00 FL	*280.00 FL
7	1		*SET CRASH BAR	Dented	320.00 FL	*320.00 FL
8	1		*HANDLE BAR	Bent	290.00 FL	*180.00 FL
9	1		*VISOR	Cut	280.00 FL	*215.00 FL
10	1		*CLUTCH LEVER	Dented	90.00 FL	*90.00 FL
11	1		*FORK TUBE	Serviceable	1,200.00 FL	*- FL
12	1		*BRAKE LEVER	Serviceable	95.00 FL	*- FL
13	1		*BELLY PAN	Cracked	350.00 FL	*350.00 FL
14	1		*EXHAUST GUARD	Dented	290.00 FL	*290.00 FL
15	1		*MIRROR LH	Dented / Cut	190.00 FL	*160.00 FL
16	1		*HEADLAMP ASSY (STANLEY)	Dented / Cut	1,250.00 FL	*565.00 FL
17	1		*REAR SIGNAL RH	Serviceable	190.00 FL	*- FL
18	1		*TAIL LIGHT	Cut	280.00 FL	*253.00 FL
19	1		*REAR NUMBER PLATE	Bent	18.00 FS	*18.00 FS
20	1		*IU UNIT	Dented	170.00 FS	*170.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,933.00	4,901.00
- List Item Discount on L Items 10.00/10.00% (S\$)	774.50	471.30
Total Parts (S\$)	7,158.50	4,429.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	35.00
2	REMOVE AND REPLACE NECESSARY PARTS ,ALIGN ETC	New	250.00	150.00
3	REMOVE AND REPLACE FORK TUBE SUPPLY FORK OIL AND REPLACE EXHAUST PIPE	New	180.00	0.00
Gross Labour Cost (S\$)			470.00	185.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >