

Your Ref : SNM22D204621/C01

Date: 12th July 2022

Our Ref : CS/CTI22006340/Tvy3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMV 3391G
ACCIDENT ON 01/07/2022**

Instruction was received to inspect the vehicle Reg. No. SMV 3391G. The inspection was conducted on 05/07/2022 at the premises of M/s Car City Auto Centre Pte Ltd, Blk 9006 Tampines St 93 #01-198, Singapore 528840.

The following vehicle information was recorded:

Registration Number	: SMV 3391G
Make/Model	: Mercedes Benz A180 (R17)
Year of Registration	: 2015
Body Colour	: Bronze
Chassis Number	: WDD1760422J351515
Engine Capacity	: 1595 cc
Speedometer Reading	: 127922 km

The vehicle sustained damages at the front portion. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 60,000.00 (est)
Less: LTA Reimbursement Value (RV)	S\$ 25,764.00
Nett Liability	<u>S\$ 34,236.00</u> =====

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.