

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 7204G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER (CONSISTENT) | TORN | 1,350.00 | 880.00 |
| 1 | REAR BUMPER TOW HOOK COVER RH (CONSISTENT) | NOT NECESSARY | 30.00 | - |
| 2 | REAR BUMPER SIDE RETAINER (FRONT) @\$78.10 (CONSISTENT) | O/S CRACKED | 156.20 | 78.10 |
| 2 | REAR BUMPER SIDE RETAINER (REAR) @\$80.00 (CONSISTENT) | NOT NECESSARY | 160.00 | - |
| 1 | REAR BUMPER SIDE SPONGE RH (CONSISTENT) | CRACKED | 110.00 | 110.00 |
| 1 | REAR BUMPER COVER EXHAUST GARNISH (CONSISTENT) | NOT NECESSARY | 95.00 | - |
| 1 | REAR BUMPER REFLECTOR RH (CONSISTENT) | NOT NECESSARY | 89.00 | - |
| 1 | TAIL LAMP RH (CONSISTENT) | NOT NECESSARY | 350.00 | - |
| 1 | REAR FENDER RH (CONSISTENT) | TO REPAIR SEE LABOUR | 980.00 | - |
| 1 | REAR FENDER INNER TRIM RH (CONSISTENT) | NOT NECESSARY | 1,370.00 | - |
| 1 | REAR FENDER AIR CON BLOWER C/W MOTOR (CONSISTENT) | CRACKED | 2,980.00 | 2,289.00 |
| 1 | REAR FENDER 1/4 GLASS MOULDING (CONSISTENT) | NOT NECESSARY | 910.00 | - |
| 1 | REAR FENDER LOWER PANEL RH (CONSISTENT) | TO REPAIR SEE LABOUR | 340.00 | - |
| 1 | REAR FENDER COWLING RH (CONSISTENT) | TORN | 95.00 | 95.00 |
| 1 | REAR SHOCK ABSORBER RH (CONSISTENT) | NOT NECESSARY | 395.00 | - |
| 1 | REAR WHEEL HUP WITH BEARING RH(CONSISTENT) | DAMAGED | 995.00 | 672.00 |
| 1 | REAR AXLE (CONSISTENT) | NOT NECESSARY | 3,150.00 | - |
| | LESS 25% DISCOUNT | | -3,388.80 | -1,031.03 |
| | | | 10,166.40 | 3,093.07 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET REAR BUMPER CLIPS (SN) (CONSISTENT) | NECESSARY | 50.00 | 30.00 |
| 1 | SET REAR BUMPER REFLECTOR (SPECIAL TYPE) (SN) (CONSISTENT) | NOT NECESSARY | 250.00 | - |
| 1 | SET TAIL LAMP CLIP (SN) (CONSISTENT) | NOT NECESSARY | 30.00 | - |
| 1 | REAR FENDER RH SEALANT (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | SET REAR FENDER INNER TRIM CLIP (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |

Report Ref No. CC4/ASM22006343/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|----------------------|
| 1 | SET REAR FENDER INNER COWLING CLIP (SN) (CONSISTENT) | NECESSARY | 50.00 | 10.00 |
| 1 | REAR FENDER GLASS RH SEALANT (SN) (CONSISTENT) | NOT NECESSARY | 60.00 | - |
| 1 | REAR FENDER GLASS SEALANT RH INNER SEAL (SN) (CONSISTENT) | NOT NECESSARY | 40.00 | - |
| 1 | SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT) | NOT NECESSARY | 30.00 | - |
| 1 | SET REAR EXHAUST COVER GARNISH CLIP (SN) (CONSISTENT) | NOT NECESSARY | 30.00 | - |
| 4 | REVERSE SENSOR (SN) (CONSISTENT) | NOT NECESSARY | 360.00 | - |
| 1 | REAR WHEEL TYRE RH (SN) (CONSISTENT) | CUT | 650.00 | 200.00 |
| 1 | REAR WHEEL RIM RH (SN) (CONSISTENT) | CUT | 1,500.00 | 650.00 |
| 1 | SET WHEEL CAP (SN) (CONSISTENT) | NOT NECESSARY | 120.00 | - |
| 1 | BRAKE OIL (SN) (CONSISTENT) | NOT NECESSARY | 50.00 | - |
| | | | 3,350.00 | 890.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND REAR FENDER LOWER PANEL RH . | | 1,600.00 | 400.00 |
| | TO SPRAY PAINT AFFECTED AREA. | | 1,200.00 | 400.00 |
| | TUFF COAT. | | 250.00 | 40.00 |
| | REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR . | | 180.00 | 50.00 |
| | REMOVE AND REFIX REAR AIRCON BLOWER MOTOR . | | 350.00 | 180.00 |
| | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING. | | 80.00 | 50.00 |
| | REMOVE AND REFIX REAR QUATER GLASS RH . | NOT NECESSARY | 100.00 | - |
| | CONDUCT WATER LEAKAGE TEST . | NOT NECESSARY | 100.00 | - |
| | REMOVE AND REFIX REAR UNDERCARRIAGE. | | 350.00 | 60.00 |
| | FOUR WHEEL ALIGHMENT . | | 120.00 | 80.00 |
| | RESET ABS LIGHT . | NOT NECESSARY | 350.00 | - |
| | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC. | NOT NECESSARY | 180.00 | - |
| | | | 4,860.00 | 1,260.00 |
| | GRAND TOTAL | | 18,376.40 | 5,243.07 |

Report Ref No. CC4/ASM22006343/Apa3q2



Page No.:3 of 3

| RECOMMENDED COST OF LUMP SUM REPAIRS | 4,200.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CC4/ASM22006343/Apa3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.