

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22006351/RCY3M4**Date:** 28/07/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000794		
<b>Claimant Vehicle No :</b>	SHC332G	<b>Insured Vehicle No :</b>	SND6443D		
Date of Loss:	02/07/2022	Nature of Claim:	TP	Claim No:	M2203459

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC332G</b>	Engine No:	G4LEKU385606
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU183135
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,222.92	772.12	2,450.80	76.04
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,000.00	1,760.00	1,240.00	41.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,233.92</b>	<b>2,543.12</b>	<b>3,690.80</b>	<b>59.21</b>
<b>+ GST 7.00/7.00% (S\$)</b>	436.37	178.02	258.35	59.20
<b>Nett Amount (S\$)</b>	<b>6,670.29</b>	<b>2,721.14</b>	<b>3,949.15</b>	<b>59.21</b>

**INSPECTION**

Date of Assignment:	04/07/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	04/07/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD RASUL**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
<b>Parts:</b>	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC332G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Repair	2,147.90 FL	*- FL
2	1		*REAR WHEEL CAP LH	Scratched	346.40 FL	*346.40 FL
3	1		*ROCKER PANEL GARNISH LH	Repair	915.60 FL	*- FL
4	1		*FRT DOOR COMFORTDELGRO LH	Necessary	75.00 F	*75.00 F
5	1		*REAR DOOR APPS LH	Necessary	80.00 F	*80.00 F
6	1		*FRT DOOR ADV.STICKER LH	Necessary	100.00 F	*100.00 F
7	1		*REAR DOOR ADV.STICKER LH	Necessary	100.00 F	*100.00 F
8	1		*REAR FENDER ADV.STICKER LH	Necessary	100.00 F	*100.00 F
9	1		*REAR FENDER (PETROL ONLY) LH	Necessary	40.00 F	*40.00 F
					<b>Sub Total (\$\$)</b>	<b>3,904.90</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>681.98</b>
					<b>Total Parts (\$\$)</b>	<b>3,222.92</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING-Rear Fender LH Etc	New	1,200.00	700.00
2	SPRAY PAINTING-Frt Door LH & Rear Bumper Etc	New	1,500.00	1,000.00
3	TUFF KOTE	New	60.00	0.00
4	TRANSFER OF DOOR	New	120.00	0.00
5	WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			3,000.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >