

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN		ef:	CS3/SMO22006354/Evy3m4		
	50 RAFFLES PLAC SINGAPORE LAND	Da	ate:	07/07/2022		
			Co	ode:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	FBL 8367C	Veh. Inspected		FBP 8948E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2202299/SYH	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		04/07/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA MX KING	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MH3UG0750KK024615	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	60/80-17	PIRELLI		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/80-17	PIRELLI		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.					
5.	5. General Information					
	Accident Date	24/06/2022	Inspect Date / Tin	ne	05/07/2022 (12:49 PM)	
	Survey held at	SPEEDWAY MOTOR PL				
		36 TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00-\$3,000.00					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	3 '	Worki	ng Days	

Report Ref No. CS3/SMO22006354/Evy3m4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser