LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22006356/KCY3E2

25/07/2022 Date:

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SLA3604R Insured Vehicle No: GBE8059D

No:

Date of Loss: 30/06/2022 Nature of Claim: TP Claim No: CDMCG22001268

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA3604R**

Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 1ZRY219485

Reg. Date: 27/02/2016 (Man. Year: 2015) Chassis No: MR053REH104540264

Colour: Metallic Silver Odometer: 128925 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 7 mm Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|------------|--------|
| Parts | | 4,309.74 | 2,356.41 | 1,953.33 | 45.32 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 2,820.00 | 1,170.00 | 1,650.00 | 58.51 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 7,129.74 | 3,526.41 | 3,603.33 | 50.54 |
| | Approved Total (Overridden) (S\$) | | 2,800.00 | | |
| | Nett Amount (S\$) | 7,129.74 | 2,800.00 | 4,329.74 | 60.73 |

INSPECTION

04/07/2022 Date of Assignment:

Ngs Automotive (HQ) Date Inspected: 04/07/2022 Inspected At:

BLK 10 AMK IND PK 2A #02-01

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **CELINE FONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jul 2022)

Parts: 143 TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA3604R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------------------|--|-------------------------|------------|------------|
| 1 | 1 | *REAR BOOT LID | Bent | 783.90 FL | *783.90 FL |
| 2 | 1 | *BOT LAMP RH / LH | O/S Cut | 586.36 FL | *293.18 FL |
| 3 | 2 | *TAILLAMP RH / LH | Serviceable | 771.60 FL | *- FL |
| 4 | 1 | *REAR BUMPER | Buckled | 573.30 FL | *573.30 FL |
| 5 | 1 | *REINFORCEMENT, RR BUMPER | Bent | 336.20 FL | *336.20 FL |
| 6 | 2 | *ARM, REAR BUMPER RH / LH | Serviceable | 121.60 FL | *- FL |
| 7 | 2 | *RETAINER RH / LH UPP | Serviceable | 143.40 FL | *- FL |
| 8 | 2 | *RETAINER SIDE RH / LH | Serviceable | 140.00 FL | *- FL |
| 9 | 1 | *END PANEL | Repair | 655.60 FL | *- FL |
| 10 | 1 | *END PANEL GARNISH | Mtg Cracked | 236.50 FL | *236.50 FL |
| 11 | 1 | *LUGGAGE COMPARTMENT PANEL (NPA) | Repair | 0.00 FL | *- FL |
| 12 | 1 | *RUBBER, TRUNK | Serviceable | 196.88 FL | *- FL |
| 13 | 1 | *SET REVERSE SENSOR RH / LH (ORIGINAL) | Dented | 499.62 FL | *396.00 FL |
| 14 | 1 | *EMBLEM BADGE | Necessary | 59.00 FL | *59.00 FL |
| 15 | 1 | *EMBLEM CORROLLA | Necessary | 56.70 FL | *56.70 FL |
| 16 | 1 | *EMBLEM ALTIS | Necessary | 62.00 FL | *62.00 FL |
| 17 | 1 | *LOCK, RR BOOT INNER | Dented | 357.00 FL | *285.10 FL |
| 18 | 20 | *CLIPS, RR TRIM | Not Necessary | 100.00 FL | *- FL |
| 19 | 1 | *NO PLATE C/W CASING | Dented | 50.00 FS | *45.00 FS |
| F=Fra | anchise part. S=Spc | Nett. L=ListItemDisc. | - | | |
| | | | Sub Total (S\$) | 5,729.66 | 3,126.88 |
| | | - List Item Discount on L I | tems 25.00/25.00% (S\$) | 1,419.92 | 770.47 |
| | | | Total Parts (S\$) | 4,309.74 | 2,356.41 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|--|---------------|------------|--------|
| <u>Lab</u> | our Items | | | |
| 1 | TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT / ATTACHMENT, REPAIR / RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION | New | 1,400.00 | 500.00 |
| 2 | TRANSFER TAILGATE MECHANISM | New | 180.00 | 50.00 |
| 3 | SPRAY PAINTING | New | 1,200.00 | 600.00 |
| 4 | TO CHECK ALL WIRE HARNESS, ALL RELATED CONNECTORS. CHECK PROPER FUNCTION | New | 40.00 | 20.00 |
| | Gross Labo | 2,820.00 | 1,170.00 | |
| | Report was unsubmitted during th | is print-out. | | |

< END OF ESTIMATES >