

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006359/GCY3Q2**Date:** 11/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00195102100
<b>Claimant Vehicle No :</b>	SMD8382U	<b>Insured Vehicle No :</b>	SNB5034T
Date of Loss:	29/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204596

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMD8382U</b>	Engine No:	4B40DL5652
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)	Chassis No:	JMAXTGK1WJZ001688
Reg. Date:	07/09/2018 (Man. Year: 2018)	Odometer:	56694 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/70 R16	Rear Tyre Size:	215/70 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	246.60	246.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	850.00	210.00	19.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,306.60</b>	<b>1,096.60</b>	<b>210.00</b>	<b>16.07</b>
<b>+ GST 8.00/8.00% (S\$)</b>	104.53	87.73	16.80	16.07
<b>Nett Amount (S\$)</b>	<b>1,411.13</b>	<b>1,184.33</b>	<b>226.80</b>	<b>16.07</b>

**INSPECTION**

Date of Assignment:	04/07/2022		
Date Inspected:	06/07/2022	Inspected At:	Vins Automotive Group (HQ) 160 SIN MING DRIVE #03-03 Singapore 575722
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2023)
Parts:	143	MITSUBISHI ECLIPSE CROSS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD8382U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR LOWER PROTECTOR	Scratched	173.00 FL	*173.00 FL
2	1		*REAR LH DOOR LOWER PROTECTOR	Scratched	101.00 FL	*101.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	274.00 274.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	27.40 27.40
					Total Parts (S\$)	246.60 246.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR DAMAGES	New	380.00	200.00
2	TO SPRAY PAINTING	New	680.00	650.00
<b>Gross Labour Cost (S\$)</b>			<b>1,060.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >