

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22006360/ECY3E2

Date: 01/09/2022

REFERENCE

Insured/Claimant: T.T.CHUA CONSTRUCTION PTE LTD Policy No: DMCG21008903
Date of Loss: 29/06/2022 Nature of Claim: OD Claim No: CDMCG22001278

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD2842T**
Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M) Engine No: 6M70417726
Reg. Date: 18/08/2008 (Man. Year: 2008) Chassis No: FV51JJA00304
Colour: White Odometer: 0 km
Engine Capacity: 12882 cc
Market Value/New Car Price: S\$23,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5
Front Left Side: HELLOWAY 4 mm Rear Left Side: HELLOWAY 4 mm
Front Right Side: HELLOWAY 4 mm Rear Right Side: HELLOWAY 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,696.30	31,023.30	2,673.00	7.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,180.00	3,500.00	2,680.00	43.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,876.30	34,523.30	5,353.00	13.42
Approved Total (Overridden) (S\$)		19,000.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
Nett Amount (S\$)	39,876.30	17,000.00	22,876.30	57.37

INSPECTION

Date of Assignment: 04/07/2022 Present Location: Lee Kuan Hwa Motor Service (Gul Crescent)
Date Inspected: 05/07/2022 Inspected At: Lee Kuan Hwa Motor Service (Gul Crescent)
20 Gul Crescent
Singapore 629529
Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Sep 2022)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD2842T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CABIN (WCP)	Dented	19,000.00 F	*19,000.00 F
2	1		*CABIN CROSS MEMBER (WCP)	Bent	1,285.00 F	*1,285.00 F
3	2		*AIR PUMP LH & RH, CABIN (WCP)	Crushed	600.00 F	*600.00 F
4	2		*AIR PUMP BRACKET LH & RH, CABIN (WCP)	Bent	560.00 F	*560.00 F
5	2		*CABIN ABSORBER LH, RH (WCP)	Bent	240.00 F	*240.00 F
6	1		*INTERCOOLER (WCP)	Bent	2,500.00 F	*2,500.00 F
7	1		*RADIATOR (WCP)	Bent	1,200.00 F	*1,200.00 F
8	1		*RADIATOR FAN COWLING (WCP)	Not Necessary	480.00 F	*- F
9	1		*ENGINE FAN (WCP)	Broken	680.00 F	*680.00 F
10	1		*ENGINE FAN CLUTCH (WCP)	Not Necessary	1,250.00 F	*- F
11	1		*FRONT BUMPER (WCP)	Bent	1,750.00 F	*1,750.00 F
12	1		*FRONT BUMPER TOP PROTECTOR (WCP)	Broken	185.00 F	*185.00 F
13	1		*FRONT BUMPER CENTER COVER (WCP)	Missing	105.00 F	*105.00 F
14	1		*Headlamp BEZEL RH (WCP)	Broken	98.00 F	*98.00 F
15	1		*CHASSIS CROSS MEMBER (WCP)	Not Necessary	700.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	30,633.00	28,203.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	3,063.30	2,820.30
Total Parts (\$\$)	33,696.30	31,023.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICES 2 TRIPS	New	360.00	200.00
2	WIRING SERVICES	New	300.00	200.00
3	CRANES SERVICES	New	320.00	0.00
4	REMOVE & REFIX INTERCOOLER & RADIATOR FAN	New	1,200.00	300.00
5	LABOUR CHARGES	New	2,800.00	1,800.00
6	SPRAY PAINTING	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			6,180.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >