

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22006362/UVY3E2

Date: 04/08/2022

REFERENCE

Insured/Claimant: KOK MUN LOONG Policy No: SP2001918221
Date of Loss: 29/06/2022 Nature of Claim: OD Claim No: 202222005456KC-S

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML8310K**
Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: A25A5071140
Reg. Date: 06/06/2019 (Man. Year: 2018) Chassis No: JTNB23HK803017228
Colour: White Odometer: 102207 km
Engine Capacity: 2487 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,056.50	4,375.80	2,680.70	37.99
Miscellaneous Items	60.00	20.00	40.00	66.67
Labour	1,910.00	1,580.00	330.00	17.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,026.50	5,975.80	3,050.70	33.80
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	9,026.50	5,375.80	3,650.70	40.44
+ GST 7.00/7.00% (S\$)	631.86	376.31	255.55	40.44
Nett Amount (S\$)	9,658.36	5,752.11	3,906.25	40.44

INSPECTION

Date of Assignment: 04/07/2022 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 05/07/2022 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2022)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML8310K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Repair	450.00 F	*- F
2	10		*INSULATOR CLIP (WCP)	Not Necessary	20.00 F	*- F
3	1		*FRT GRILLE (WCP)	Cut	350.00 F	*350.00 F
4	1		*FRT GRILLE LOGO (WCP)	Not Necessary	425.00 F	*- F
5	1		*FRT BUMPER (WCP)	Torn	355.00 F	*355.00 F
6	1		*FRT BUMPER RETAINER LH (WCP)	Cracked	45.00 F	*45.00 F
7	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
8	1		*FRT BUMPER INNER SPONGE (WCP)	Torn	105.00 F	*105.00 F
9	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	210.00 F	*210.00 F
10	1		*FRT BUMPER CENTER GRILLE (WCP)	Grazed	195.00 F	*195.00 F
11	1		*CENTER GRILLE SIDE MOULDING LH (BELOW HEADLAMP) (WCP)	Cracked	95.00 F	*95.00 F
12	1		*FRT BUMPER TOW COVER (WCP)	Torn	38.00 F	*38.00 F
13	1		*FRT BUMPER LOWER CTR MOULDING (WCP)	Scratched	135.00 F	*135.00 F
14	1		*FRT BUMPER LOWER SIDE MOULDING LH (WCP)	Scratched	95.00 F	*95.00 F
15	1		*FOG LAMP COVER LH (WCP)	Torn	145.00 F	*145.00 F
16	1		*HEADLAMP (WCP)	N/S Cracked / O/S Not Necessary	2,800.00 F	*1,400.00 F
17	6		*SUPPORT TOP GARNISH CLIP (WCP)	Not Necessary	12.00 F	*- F
18	1		*NUMBER PLATE GARNISH (WCP)	Not Necessary	95.00 F	*- F
19	1		*FRT FENDER HYBRID PLATE LH (WCP)	Not Necessary	35.00 F	*- F
20	1		*FRT BUMPER TOP SEAL (WCP)	Necessary	65.00 F	*65.00 F
Supplementary #1						
21	1		*AIR BUFFER (WCP)	Torn	245.00 F	*245.00 F
22	1		*FRT BUMPER REINFORCEMENT BRACKET LH (WCP)	Dented	55.00 F	*55.00 F
23	1		*AIRCON SIDE DEFLECTOR LH (WCP)	Torn	85.00 F	*85.00 F
24	1		*LH HEADLAMP PANEL (WCP)	Bent	145.00 F	*145.00 F
Supplementary #2						
25	1		*FRT LH CHASIS FRT JOINT (WCP)	Badly Dented	195.00 F	*195.00 F

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT NUMBER PLATE (SERVICEABLE)	40.00	0.00
Supplementary #1				
2	1	RADIATOR COOLANT (NECESSARY)	20.00	20.00
Sub Total (\$\$)			60.00	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX FRT PARKING SENSOR	New	80.00	40.00
3	LABOUR CHARGE	New	650.00	520.00
4	SPRAY PAINTING	New	750.00	600.00
Supplementary #1				
Labour Items				
5	REPLACE AND SPRAY FRT LH CHASIS JOINT AND REPAIR CHASIS	New	300.00	300.00
6	REMOVE AND REFIX AIRCON AND GAS	New	100.00	100.00
Gross Labour Cost (\$\$)			1,910.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >