

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006363/GVY3Q2**Date:** 14/11/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00030352200
Claimant Vehicle No :	GBJ1118L	Insured Vehicle No :	GBE7130L
Date of Loss:	24/06/2022	Nature of Claim:	TP
		Claim No:	SNM22D204627/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ1118L	Engine No:	1KD2832233
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35YX0K211911
Reg. Date:	02/01/2019 (Man. Year: 2018)	Odometer:	62526 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,490.27	1,445.02	2,045.25	58.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	530.00	2,360.00	81.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,380.27	1,975.02	4,405.25	69.04
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	6,380.27	1,550.00	4,830.27	75.71
+ GST 7.00/7.00% (S\$)	446.62	108.50	338.12	75.71
Nett Amount (S\$)	6,826.89	1,658.50	5,168.39	75.71

INSPECTION

Date of Assignment:	03/08/2022	
Date Inspected:	05/07/2022	Inspected At: 39 woodlands close #01-12 Mega@woodlands
Estimated Period of Repair:	3.0 days	Repairer: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Nov 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1118L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	55.00 FN	*- FN
2	1		*REAR TAILLAMP LH	Not Necessary	292.50 FN	*- FN
3	1		*REAR TAILLAMP RH	Cut	292.50 FN	*292.50 FN
4	1		*REAR TAILBOARD TOYOTA EMBLEM	Necessary	85.00 FN	*85.00 FN
5	1		*REAR TAILBOARD BOTTOM LOCK LH	Bent	115.00 FN	*115.00 FN
6	1		*REAR TAILBOARD BOTTOM LOCK RH	Bent	115.00 FN	*115.00 FN
7	1		*REAR EXHAUST PIPE	Not Necessary	1,050.00 FL	*- FL
8	1		*REAR TAILBOARD	Buckled	1,137.70 FL	*1,137.70 FL
9	1		*REAR FLOOR PANEL	Not Necessary	1,100.00 FL	*- FL
10	1		*REAR NUMBER PLATE	Bent	45.00 FS	*15.00 FS
11	1		*REAR 70KM/H STICKER	Necessary	60.00 FS	*15.00 FS
12	1		*REAR 6 PAX STICKER	Necessary	60.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	4,407.70	1,790.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	821.93	284.43
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	95.50	60.75
Total Parts (\$\$)	3,490.27	1,445.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS REPLACE DAMAGED PARTS	New	30.00	30.00
2	TO TRANSFER REAR TAILGATE	New	80.00	0.00
3	TO REMOVE AND REFIT ,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	280.00	0.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	200.00
5	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,000.00	300.00
Gross Labour Cost (\$\$)			2,890.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >