

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006367/DVY3Q2**Date:** 14/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00067372100		
Claimant Vehicle No :	PC5869Y	Insured Vehicle No :	YQ3938P		
Date of Loss:	01/07/2022	Nature of Claim:	TP	Claim No:	SNM22D204612/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC5869Y		Engine No:	1KD2673967
Make & Model:	TOYOTA HIACE, 3.0 D (M)		Chassis No:	KDH2230030443
Reg. Date:	27/06/2017 (Man. Year: 2016)		Odometer:	302131 km
Colour:	Silver			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Condor 5 mm	Rear Left Side:	Condor 5 mm
Front Right Side:	Condor 5 mm	Rear Right Side:	Condor 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,068.15	5,970.97	26,097.18	81.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	1,030.00	4,670.00	81.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,768.15	7,000.97	30,767.18	81.46
Approved Total (Overridden) (\$\$)		5,600.00		
(\$\$)	37,768.15	5,600.00	32,168.15	85.17
+ GST 7.00/7.00% (\$\$)	2,643.77	392.00	2,251.77	85.17
Nett Amount (\$\$)	40,411.92	5,992.00	34,419.92	85.17

INSPECTION

Date of Assignment:	05/07/2022	
Date Inspected:	05/07/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Oct 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5869Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEAD LAMP LH/RH	Mtg Cracked	7,378.20 FL	*4,841.00 FL
2	2		*HEAD LAMP WIREHARNES LH/RH	Not Necessary	3,782.58 FL	*- FL
3	1		*BONNET	Dented	1,180.51 FL	*1,020.30 FL
4	1		*BONNET TOYOTA LOGO	Necessary	79.10 FL	*79.10 FL
5	1		*BONNET SEAL	Serviceable	81.92 FL	*- FL
6	1		*BONNET LOCK	Bent	583.00 FL	*128.00 FL
7	2		*BONNET HINGE LH/RH	Repair	382.00 FL	*- FL
8	1		*BONNET STAND	Not Necessary	147.00 FL	*- FL
9	1		*FRONT GRILLE ASSY	Mtg Broken	1,082.60 FL	*581.10 FL
10	1		*FRONT BOTTOM	No such part	829.00 FL	*- FL
11	1		*FRONT GRILLE TOP CHROME	Not Necessary	329.00 FL	*- FL
12	1		*FRONT GRILLE CENTER CHROME	Not Necessary	316.00 FL	*- FL
13	1		*FRONT GRILLE BOTTOM CHROME	Not Necessary	337.50 FL	*- FL
14	1		*FRONT BUMPER	Not Necessary	849.80 FL	*- FL
15	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	385.91 FL	*- FL
16	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	206.80 FL	*- FL
17	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	821.18 FL	*- FL
18	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	69.80 FL	*- FL
19	2		*FRONT BUMPER PARKING SENSOR	Not Necessary	649.00 FL	*- FL
20	1		*FRONT INTER COOLER ASSY	Punctured	3,492.84 FL	*1,108.60 FL
21	1		*FRONT INTER COOLER ASSY OUTER GARNISH	Cut	392.00 FL	*183.20 FL
22	1		*FRONT RADIATOR ASSY	Not Necessary	2,149.85 FL	*- FL
23	1		*FRONT RADIATOR FAN MOTOR	Not Necessary	526.84 FL	*- FL
24	1		*FRONT RADIATOR FAN MOTOR COWLING	Not Necessary	498.80 FL	*- FL
25	1		*FRONT RADIATOR FAN BLADE	Not Necessary	244.50 FL	*- FL
26	1		*FRONT BUMPER SPARE TANK	Not Necessary	298.00 FL	*- FL
27	1		*FRONT WIPER WASHER TANK	Not Necessary	178.10 FL	*- FL
28	1		*FRONT A/C CONDENSOR ASSY	Not Necessary	1,986.70 FL	*- FL
29	1		*FRONT A/C HIGH PRESSURE HOSE	Not Necessary	398.40 FL	*- FL
30	1		*FRONT A/C LOW PRESSURE HOSE	Not Necessary	681.20 FL	*- FL
31	1		*FRONT A/C DISCHARGE HOSE	Not Necessary	894.54 FL	*- FL
32	2		*FRONT A/C CONDENSOR SIDE COWLING LH/RH	Not Necessary	508.20 FL	*- FL
33	1		*FRONT SUPPORT PANEL	Repair	1,782.50 FL	*- FL
34	1		*FRONT BRACE PANEL	Not Necessary	149.80 FL	*- FL
35	1		*FRONT REINFORCEMENT BAR UPPER	Not Necessary	984.52 FL	*- FL
36	1		*FRONT REINFORCEMENT BAR LOWER	Not Necessary	699.81 FL	*- FL
37	1		*FRONT REINFORCEMENT BAR BRACKET (TOP)	Not Necessary	1,094.50 FL	*- FL
38	1		*FRONT RADAR ASSY	Not Necessary	3,895.15 FL	*- FL
39	1		*FRONT RADAR BRACKET	Not Necessary	984.05 FL	*- FL
40	1		*FRONT WIPER GARNISH	Not Necessary	693.00 FL	*- FL
41	1		*FRONT NO PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
42	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
43	1		*LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*RADIATOR COOLANT	Not Necessary	200.00 FS	*- FS
45	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

10/14/22, 3:24 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					42,574.20	7,956.30
- List Item Discount on L Items 25.00/25.00% (S\$)					10,506.05	1,985.33
Total Parts (S\$)					32,068.15	5,970.97
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	20.00
5	TO RNR INTER -COOLER TO FACILITATE REPAIRS	New	200.00	80.00
6	TO RNR FRONT RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR FRONT A/C CONDENSOR & REFILL A/C GAS TO FACILITATE REPAIRS	New	200.00	0.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,700.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >