12/20/22, 9:54 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI22006376/KCY3M4

20/12/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer: (Singapore) Pte. Ltd.

Policy No: DMPCSNW00196212100

Claimant Vehicle

SCL813Y

Insured Vehicle SDS7228S

No:

Odometer:

Date of Loss:

Reg. Date:

Nature of Claim: TP 24/06/2022

Claim No:

SNM22D204544/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

SCL813Y Reg No:

BMW M6, 4.4 SMT 2DR ABS LED DSC NAV Make & Model:

Engine No: 20710156S63B44B

69725 km

HUD (A)

17/09/2012 (Man. Year: 2012) Chassis No:

No:

WBSLZ92070C967409

Colour: Metallic Black

Engine Capacity: 4395 cc

Market Value/New Car

N/A

Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Sum Insured (S\$):

Front Tyre Size: 265/35 ZR20 Rear Tyre Size: 295/30 ZR20 Front Left Side: Rear Left Side: Michelin 4 mm Michelin 4 mm Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/07/2022

THIAM HENG HUAT PTE LTD Date Inspected: 05/07/2022 Inspected At:

176 SIN MING DRIVE

#05-14 SINGAPORE 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG **CELINE FONG** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 -\$11,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2022)

Parts: M1-COUPE BMW M6 4.4 SMT 2DR ABS LED DSC NAV HUD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCL813Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

12/20/22, 9:54 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >