

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1167R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER-FRT FOG LP - LH (DISC 10%)	CRACKED	40.24	36.22
1	HEADLAMP ASM -LH (DISC 10%)	CRACKED	1,098.86	988.97
1	LINER ASM-FRT W/H - LH (DISC 10%)	SCRATCHED	125.22	112.70
1	FASCIA-FRT BPR (DISC 10%)	DEFORMED	721.66	649.49
1	BRACKET-FRT BPR FASCIA - LH (DISC 10%)	CRACKED	23.08	20.77
1	FINISHER-FRT BPR - LH (DISC 10%)	CRACKED	98.80	88.92
1	GRILLE-FRT BPR FASCIA LOWER	NOT NECESSARY	149.03	-
1	FINISHER-FRT BPR LOWER - LH	NOT NECESSARY	20.38	-
1	FINISHER-FRT FOG LP CVR - LH	NOT NECESSARY	47.32	-
1	BRACKET-FRT BPR FASCIA - LH	NOT NECESSARY	23.08	-
1	FINISHER-FRT BPR - LH	NOT NECESSARY	98.80	-
1	PANEL ASM-LEG CTHR	NOT NECESSARY	131.04	-
1	BAR ASM-FRT BPR IMP	NOT NECESSARY	624.00	-
1	GRILLE ASM-RAD	NOT NECESSARY	978.02	-
1	FENDER ASM-FRT - LH	TO REPAIR SEE LABOUR	379.80	-
			4,559.33	1,897.07
	<u>LABOUR</u>			
	PANEL BEATING AND BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER ASM-FRT - LH.		1,200.00	300.00
	SPRAY PAINT.		856.00	440.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	150.00
	ISOLATED OF (EV) (NET).		150.00	150.00
			2,936.00	1,040.00
	GRAND TOTAL		7,495.33	2,937.07

Report Ref No. NS/INC22006378/Rqcm4





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)

2,937.07

Report Ref No. NS/INC22006378/Rqcm4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser