



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 1280Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,836.90	-
2	REAR BUMPER SIDE RETAINER @\$150.60	NOT NECESSARY	301.20	-
2	REAR BUMPER REFLECTOR @\$124.00	NOT NECESSARY	248.00	-
1	REAR BUMPER LH CHROME	NOT NECESSARY	155.25	-
1	REAR BUMPER DIFFUSER	NOT NECESSARY	586.00	-
1	TAILLAMP (LH)	CRACKED	985.60	691.20
	LESS 10% DISCOUNT		-411.30	-69.12
			3,701.65	622.08
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
			490.00	-
<u>LABOUR</u>				
	REMOVE & REFIT REVERSE SENSOR & TEST. }		100.00	40.00
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNET. }		100.00	-
	TO APPLY UNDERCOATING & RUST ROOFING.	NOT NECESSARY	100.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		500.00	300.00
	SPRAY PAINTING.		600.00	500.00
			1,400.00	840.00
GRAND TOTAL			5,591.65	1,462.08
RECOMMENDED COST OF REPAIRS				1,462.08

Report Ref No. CS/SMO22006386/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.