

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22006391/VVY3Q2**Date:** 25/08/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002177834
Claimant Vehicle No :	YQ6768T	Insured Vehicle No :	SLD980H
Date of Loss:	29/06/2022	Nature of Claim:	TP
		Claim No:	202222005486KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ6768T	Engine No:	1GD8891715
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JHHAGV4630K002094
Reg. Date:	25/04/2022 (Man. Year: 2022)	Odometer:	5736 km
Colour:	Silver		
Engine Capacity:	2755 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	19 R15C	Rear Tyre Size:	19 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,240.75	4,694.80	2,545.95	35.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	2,040.00	130.00	5.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,410.75	6,734.80	2,675.95	28.44
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	9,410.75	5,400.00	4,010.75	42.62
+ GST 7.00/7.00% (S\$)	658.75	378.00	280.75	42.62
Nett Amount (S\$)	10,069.50	5,778.00	4,291.50	42.62

INSPECTION

Date of Assignment:	05/07/2022	
Date Inspected:	05/07/2022	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Aug 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ6768T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,303.50 FL	*1,303.50 FL
2	2		*TAILGATE SIDE BRACKET	Necessary	230.56 FL	*230.56 FL
3	2		*TAILGATE STOPPER	Serviceable	90.20 FL	*- FL
4	4		*TAILGATE LOWER HINGE	Dented	654.28 FL	*654.28 FL
5	1		*TAILGATE LOWER MEMBER	Dented	758.67 FL	*758.67 FL
6	2		*TAILGATE SIDE PIN	Serviceable	66.30 FL	*- FL
7	2		*TAILGATE SIDE HINGE	Bent	279.18 FL	*279.18 FL
8	2		*TAILGATE SIDE LOCK	Serviceable	353.98 FL	*- FL
9	1		*TAILGATE REINFORCEMENT	Bent	712.91 FL	*712.91 FL
10	2		*TAILLAMP PANEL	Bent	437.58 FL	*437.58 FL
11	2		*TAILLAMP	Cracked	541.64 FL	*541.64 FL
12	2		*TAILLAMP REFLECTOR	Cracked	91.96 FL	*91.96 FL
13	1		*SPARE TYRE CARRIER	Serviceable	286.99 FL	*- FL
14	2		*SPARE TYRE BRACKET	Bent	284.46 FL	*284.46 FL
15	2		*REAR NUMBER PLATE LAMP	Serviceable	129.36 FL	*- FL
16	1		*TOW HOOK	Bent	165.00 FL	*165.00 FL
17	1		*EXHAUST SILENCER	Repair	899.91 FL	*- FL
18	1		*EXHAUST SILENCER MOUNTING	Serviceable	47.85 FL	*- FL
19	1		*TAILGATE STICKER -TOYOTA	Necessary	70.00 FS	*40.00 FS
20	1		*TAILGATE STICKER -DYNA	Necessary	70.00 FS	*40.00 FS
21	1		*TAILGATE STICKER -60KM/H	Necessary	70.00 FS	*40.00 FS
22	1		*TAILGATE STICKER -13 PAX	Necessary	70.00 FS	*40.00 FS
23	1		*REAR NUMBER PLATE	Missing	60.00 FS	*40.00 FS
24	1		*REAR STEP PANEL (AFTER MARKET)	Bent	350.00 FS	*200.00 FS
25	1		*SET REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
26	1		*ALUMINIUM WOODEN BOARD	Serviceable	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,074.33	6,059.74
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,833.58	1,364.94
Total Parts (\$\$)	7,240.75	4,694.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	30.00
2	REMOVE & REPLACE TAILGATE ATTACHMENT	New	150.00	50.00
3	REMOVE & REPLACE REVERSE SENSOR	New	150.00	30.00
4	PANEL BEATING ON AFFECTED AREAS	New	100.00	600.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	800.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
7	LABOUR TO REMOVE REAR CANOPY	New	300.00	300.00
8	LABOUR TO STRAIGHTEN CHASSIS	New	200.00	200.00
Gross Labour Cost (\$)			2,170.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >