

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006393/GNY3E2**Date:** 20/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00063312200	
Claimant Vehicle No :	SNF5926Z	Insured Vehicle No :	SKA4888T	
Date of Loss:	28/06/2022	Nature of Claim:	TP	Claim No: SNM22D204548

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF5926Z		Engine No:	2ZRY836346
Make & Model:	TOYOTA COROLLA, 1.8 (A)		Chassis No:	MR2BZ3BEX00009287
Reg. Date:	09/06/2022 (Man. Year: 2022)		Odometer:	3123 km
Colour:	Blue			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,530.50	929.00	601.50	39.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	730.00	670.00	47.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,930.50	1,659.00	1,271.50	43.39
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,930.50	1,100.00	1,830.50	62.46
+ GST 7.00/7.00% (S\$)	205.14	77.00	128.14	62.46
Nett Amount (S\$)	3,135.64	1,177.00	1,958.64	62.46

INSPECTION

Date of Assignment:	05/07/2022	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Date Inspected:	05/07/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2022)
Parts:	143	TOYOTA COROLLA 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF5926Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Buckled	1,215.00 FL	*1,150.00 FL
2	2		*FRONT DOOR HINGES	Not Necessary	130.00 FL	*- FL
3	1		*FRONT FENDER LH	Repair	567.00 FL	*- FL
4	1		*FRONT FENDER EMBLEM	Necessary	62.00 FL	*62.00 FL
5	1		*FRONT DOOR INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
					Sub Total (\$\$)	2,024.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	493.50
					Total Parts (\$\$)	1,530.50
						929.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING	New	80.00	0.00
2	REMOVE AND REFIT FRONT DOOR MECHANISM	New	200.00	60.00
3	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	20.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	500.00	400.00
5	PANEL BEATING ON AFFECTED AREAS	New	500.00	250.00
Gross Labour Cost (\$\$)			1,400.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >