

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Repair Estimate


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Authorized
11 Day @ 4000\$
Repair After Rain
2 days

Make/Model: BMW 428i
Engine/Chassis No.: WBA3V32030J993174
Date of accident:
Damaged area: O/S Front

Date: 05/07/2022
Claim Type: TP
VRN: SGX58A



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper <i>1390. Bm/GM</i>	1	\$ 1,567.00	\$ 1,567.00
2	Front bumper lower lip <i>Sm</i>	1	\$ 467.00	\$ 467.00
3	Front bumper nozzle cover o/s <i>Sm</i>	1	\$ 156.00	\$ 156.00
4	Front bumper nozzle o/s <i>Sm</i>	1	\$ 268.00	\$ 268.00
5	Front bumper foglamp o/s <i>280 Mty/CM</i>	1	\$ 459.00	\$ 459.00
6	Front bumper foglamp cover o/s <i>109 mty</i>	1	\$ 275.00	\$ 275.00
7	Front bumper reinforcement <i>R</i>	1	\$ 870.00	\$ 870.00
8	Front bumper reinforcement bracket <i>R</i>	2	\$ 395.00	\$ 790.00
9	Front bumper sponge <i>in</i>	1	\$ 456.00	\$ 456.00
10	Headlamp o/s <i>2532.95 GM</i>	1	\$ 2,956.00	\$ 2,956.00
11	Headlamp support bracket o/s <i>Sm</i>	1	\$ 190.00	\$ 190.00
12	Front bumper sensor holder o/s <i>Sm</i>	1	\$ 23.00	\$ 23.00
13	Front bumper foglamp cover outer garnish o/s <i>102 mty</i>	1	\$ 195.00	\$ 195.00
Subtotal				\$ 8,672.00
List discount				5.00%
Total				\$ 8,238.40

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries <i>NA</i>	1	\$ 50.00	\$ 50.00
2	Front bumper clips <i>NA</i>	12	\$ 5.50	\$ 66.00
3	Front bumper parking sensor o/s <i>210 GM</i>	1	\$ 280.00	\$ 280.00
Total				\$ 396.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.5	\$ 100.00
3	Supply spray paint material and necessary items to respray affected area / panel.	4	\$ 800.00
4	To rust proof all affected portions after repair.	0.5	\$ ~ 100.00
Total labour			\$ 2,000.00

10,634.40