

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006412/ACY3Q2**Date:** 15/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00068102100

Claimant Vehicle No : SLS5264E **Insured Vehicle No :** SKU4982Z

Date of Loss: 01/07/2022 Nature of Claim: TP Claim No: SNM22D204630/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS5264E**

Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) Engine No: 2ZR1990506

Reg. Date: 27/09/2017 (Man. Year: 2017) Chassis No: ZVW400026228

Colour: Grey Odometer: 366783 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,181.02	7,687.65	3,493.37	31.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,200.00	1,530.00	41.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,911.02	9,887.65	5,023.37	33.69
Approved Total (Overridden) (\$\$)		7,900.00		
(\$\$)	14,911.02	7,900.00	7,011.02	47.02
+ GST 7.00/7.00% (\$\$)	1,043.77	553.00	490.77	47.02
Nett Amount (\$\$)	15,954.79	8,453.00	7,501.79	47.02

INSPECTION

Date of Assignment: 18/08/2022

Date Inspected: 05/07/2022 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2022)

Parts: 144 TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS5264E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	556.40 FL	*556.40 FL
2	2		*REAR BUMPER END SEAL COVER L/R	Deformed	184.60 FL	*184.60 FL
3	2		*REAR BUMPER REFLECTOR L/R	Cracked	116.00 FL	*116.00 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	285.60 FL	*180.00 FL
5	1		*REAR COMPARTMENT TRAY	Deformed	679.30 FL	*485.00 FL
6	1		*REAR COMPARTMENT TRAY TOP COVER	Deformed	562.50 FL	*380.00 FL
7	2		*REAR DECK BOX TOP COVER L/R	Not Necessary	762.20 FL	*- FL
8	1		*REAR END PANEL	Dented	687.30 FL	*687.30 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Cracked	485.00 FL	*165.00 FL
10	1		*REAR END PANEL INNER TOP GARNISH	Deformed	287.90 FL	*287.90 FL
11	2		*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	Cracked	1,312.00 FL	*1,312.00 FL
12	1		*REAR FLOOR PANEL	Repair	739.90 FL	*- FL
13	2		*REAR NUMBER PLATE LAMP L/R	Not Necessary	223.20 FL	*- FL
14	1		*REAR RH DECK BOX	Deformed	481.90 FL	*295.00 FL
15	1		*REAR TAILGATE	Distorted	929.60 FL	*929.60 FL
16	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	50.00 FL	*50.00 FL
17	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	52.30 FL	*52.30 FL
18	2		*REAR TAILGATE DAMPER L/R	Not Necessary	713.40 FL	*- FL
19	1		*REAR TAILGATE INNER PULL GARNISH	Not Necessary	38.50 FL	*- FL
20	1		*REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	Cracked	578.00 FL	*578.00 FL
21	1		*REAR TAILGATE MECHANISM LOCK	Damaged	425.00 FL	*425.00 FL
22	1		*REAR TAILGATE OUTER GARNISH	Cracked	427.90 FL	*427.90 FL
23	1		*REAR TAILGATE OUTER GARNISH LOGO EMBLEM	Necessary	87.10 FL	*87.10 FL
24	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	58.00 FL	*- FL
25	1		*REAR TAILGATE WEATHERSTRIP	Cut	360.70 FL	*360.70 FL
26	2		*REAR TAILGATE WINDSCREEN LOWER SEAL	Necessary	84.00 FL	*84.00 FL
27	2		*REAR TAILGATE WINDSCREEN MOULDING L/R	Necessary	130.00 FL	*130.00 FL
28	1		*REAR TAILGATE WINDSCREEN UPPER SEAL	Necessary	38.00 FL	*38.00 FL
29	2		*REAR TAILLAMP BACK RUBBER SEAL L/R	Necessary	139.00 FL	*139.00 FL
30	2		*REAR TAILLAMP L/R	Cracked	1,321.20 FL	*1,321.20 FL
31	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	118.20 FL	*118.20 FL
32	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
34	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
35	1		*REAR FLOOR PANEL INSULATOR MAT	Necessary	300.00 FS	*200.00 FS
36	1		*REAR RH REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
37	1		*SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
38	1		*REAR TAILGATE NUMBER PLATE	Bent	25.00 FS	*25.00 FS
39	1		*REAR TAILGATE NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
41	1		*SET REAR TAILGATE TOP SPOILER CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
43	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	14,409.70	10,035.20
				- List Item Discount on L Items 25.00/25.00% (\$\$)	3,228.68	2,347.55
				Total Parts (\$\$)	11,181.02	7,687.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER	New	1,400.00	800.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	1,000.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
7	TO TRANSFER REAR TAILGATE INNER TRIM BOARD ,WIPER MOTOR ,MECHANISM LOCK OUTER HANDLE	New	80.00	80.00
Gross Labour Cost (\$\$)			3,730.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >