

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22006414/KCY3M4**Date:** 31/08/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001954025

Claimant Vehicle No : SJX7942R**Insured Vehicle No :** EL1011P

Date of Loss: 02/07/2022

Nature of Claim: TP Claim No: 278206

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJX7942R**

Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)

Engine No: G4FCAU848546

Reg. Date: 13/07/2010 (Man. Year: 2010)

Chassis No: KMHU41BMAU020245

Colour: Metallic Maroon

Odometer: 195714 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Windforce 8 mm

Rear Left Side: Windforce 7 mm

Front Right Side: Windforce 8 mm

Rear Right Side: Windforce 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,638.68	4,736.24	3,902.44	45.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,270.00	950.00	29.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,858.68	7,006.24	4,852.44	40.92
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	11,858.68	5,600.00	6,258.68	52.78
+ GST 7.00/7.00% (S\$)	830.11	392.00	438.11	52.78
Nett Amount (S\$)	12,688.79	5,992.00	6,696.79	52.78

INSPECTION

Date of Assignment: 05/07/2022

Date Inspected: 06/07/2022 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive,, #03-18, Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2022)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX7942R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	886.00 FL	*- FL
2	1		*REAR BOOT LAMP RH	Dented / Cut	126.20 FL	*126.20 FL
3	1		*TAIL LAMP RH	Broken	326.20 FL	*326.20 FL
4	1		*TAIL LAMP LOWER BRACKET RH	Distorted	65.00 FL	*65.00 FL
5	1		*REAR END PANEL	Repair	485.10 FL	*- FL
6	1		*REAR BUMPER	Bent	582.20 FL	*498.00 FL
7	1		*REAR BUMPER SIDE RETAINER RH	Cracked	42.30 FL	*42.30 FL
8	1		*REAR BUMPER BRACKET RH	Repair	78.20 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	286.20 FL	*- FL
10	1		*REAR BUMPER INNER SPONGE	Cracked	141.40 FL	*141.40 FL
11	1		*REAR FENDER RH	Bent	1,503.20 FL	*1,503.20 FL
12	1		*REAR FENDER INNER PANEL RH	Repair	567.30 FL	*- FL
13	1		*REAR FENDER INNER UPHOLSTRY RH	Deformed	281.50 FL	*281.50 FL
14	1		*REAR FENDER LINER RH	Missing	172.10 FL	*172.10 FL
15	1		*REAR FENDER AIR VENT RH	Serviceable	86.30 FL	*- FL
16	1		*REAR DOOR RH	Repair	1,031.80 FL	*- FL
17	1		*REAR DOOR LOCK RH	Repair	251.10 FL	*- FL
18	1		*REAR DOOR WEATHERSTRIP RH	Serviceable	134.60 FL	*- FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	102.20 FL	*102.20 FL
20	1		*REAR SHOCK ABSORBER	Bent	285.20 FL	*285.20 FL
21	1		*REAR UPPER ARM RH	Bent	195.40 FL	*195.40 FL
22	1		*REAR LOWER ARM RH	Bent	393.20 FL	*285.00 FL
23	1		*REAR TRAILING ARM	Bent	296.50 FL	*296.50 FL
24	1		*REAR KNUCKLE ARM RH	Bent	393.20 FL	*393.20 FL
25	1		*REAR WHEEL HUB ASSY RH	Bent	363.70 FL	*230.00 FL
26	1		*REAR LINKAGE	Serviceable	64.10 FL	*- FL
27	1		*REAR STAY BAR	Bent	78.20 FL	*78.20 FL
28	1		*REAR BRAKE HOSE	Torn	55.20 FL	*55.20 FL
29	1		*REAR BRAKE SENSOR WIRE	Cut	68.50 FL	*68.50 FL
30	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
31	2		*WINDSCREEN/ QUARTER GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*SET REAR FENDER UPHOLSTRY CLIPS	Not Necessary	35.00 FS	*- FS
33	1		*SET REAR FENDER LINER CLIPS	Necessary	35.00 FS	*35.00 FS
34	1		*SET REVERSE SENSOR	Serviceable	250.00 FS	*- FS
35	1		*REAR SPORT RIM RH	Dented	450.00 FS	*280.00 FS
36	1		*REAR ROAD TIRE RH (80%)	Punctured	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,507.10	5,765.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,868.42	1,029.06
Total Parts (\$\$)	8,638.68	4,736.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE & REPLACE UPHOLSTRY, CUSHION SEAT & TRIM GARNISHES	New	200.00	100.00
3	TO REMOVE, REINSTALL REAR WINDSCREEN	New	200.00	120.00
4	TO REMOVE, REFIT FENDER QUARTER GLASS	New	80.00	50.00
5	TO REMOVE, REPLACE REAR SUSPENSION UNDERCARRIAGE PARTS	New	380.00	140.00
6	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
7	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	1,000.00	900.00
8	TO REMOVE & RENEW REVERSE SENSOR	New	80.00	50.00
9	TO RESET WHEEL ALIGNMENT	New	100.00	60.00
10	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	30.00
Gross Labour Cost (\$\$)			3,220.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >