

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22006415/PA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220018738
<b>Claimant Vehicle No :</b>	SGG9916D	<b>Insured Vehicle No :</b>	SMK3320U
Date of Loss:	02/07/2022	Nature of Claim:	TP
		Claim No:	3260026903SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGG9916D</b>	Engine No:	2AZC109292
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR507037554
Reg. Date:	27/01/2007 (Man. Year: 2006)	Odometer:	200980 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,739.82	0.00	2,739.82	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	600.00	1,800.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,139.82</b>	<b>600.00</b>	<b>4,539.82</b>	<b>88.33</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	359.79	42.00	317.79	88.33
<b>Nett Amount (\$\$)</b>	<b>5,499.61</b>	<b>642.00</b>	<b>4,857.61</b>	<b>88.33</b>
<b>+ Car Rental (4.0 x S\$160.00/day + 7.00% GST) (\$\$)</b>		684.80		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,328.80</b>		

**INSPECTION**

Date of Assignment:	08/07/2022		
Date Inspected:	08/07/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	546.20 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	170.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*O/S FRONT DOOR	Repair	1,481.00 FL	*- FL
5	1		*O/S FRONT DOOR CHROME MOULDING	Not Necessary	172.00 FL	*- FL
6	1		*O/S FRONT DOOR LOWER PROTECTOR	Repair	1,233.90 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$\$)	3,653.10 0.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	913.28 0.00
					Total Parts (\$\$)	2,739.82 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	150.00	0.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	250.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME }	New	1,000.00	600.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION }	New	1,000.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,400.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >