

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006416/GCY3Q2**Date:** 11/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00005272200
<b>Claimant Vehicle No :</b>	SLU2354M	<b>Insured Vehicle No :</b>	GBD822A
Date of Loss:	02/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204656/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLU2354M	Engine No:	R16B22001037
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650HT000619
Reg. Date:	27/11/2017 (Man. Year: 2017)	Odometer:	65090 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,087.16	1,933.38	1,153.78	37.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	2,940.00	1,540.00	34.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,567.16</b>	<b>4,873.38</b>	<b>2,693.78</b>	<b>35.60</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>605.37</b>	<b>389.87</b>	<b>215.50</b>	<b>35.60</b>
<b>Nett Amount (S\$)</b>	<b>8,172.53</b>	<b>5,263.25</b>	<b>2,909.28</b>	<b>35.60</b>

**INSPECTION**

Date of Assignment:	10/01/2023		
Date Inspected:	20/07/2022	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	4.0 days		

**Adjuster:** XING GUO QIANG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2023)
<b>Parts:</b>	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU2354M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD COMPENGINE	Bent	512.62 FS	*512.62 FS
2	1		*LOCK ASSYHOOD	Not Necessary	75.30 FS	*- FS
3	1		*CONDENSER ASSY	Cut	528.30 FS	*528.30 FS
4	1		*FACEFR.BUMPER	Cracked	434.92 FS	*434.92 FS
5	1		*BEAMR,FR.BUMPER UPPER	Not Necessary	22.87 FS	*- FS
6	1		*BEAML,FR.BUMPER UPPER	Not Necessary	22.87 FS	*- FS
7	1		*BEAM COMPFR ,RR BUMPER CENTER UPP	Bent	183.97 FS	*183.97 FS
8	1		*SPACERR.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
9	1		*SPACERL.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
10	1		*BASE ,FR.GRILLE CHROME	Cracked	63.15 FS	*63.15 FS
11	1		*MOLDINGFR.GRILLE	Cracked	85.87 FS	*85.87 FS
12	1		*EMBLEM	Necessary	12.90 FS	*12.90 FS
13	1		*NUT,PUSH 3MM (2PCS)	Necessary	3.15 FS	*3.15 FS
14	1		*RUBBERHOOD SEAL	Necessary	23.55 FS	*23.55 FS
15	1		*CLIPAMBIENT SENSOR	Broken	4.35 FS	*4.35 FS
16	1		*HEADLIGHT ASSY,R	Not Necessary	501.37 FS	*- FS
17	1		*HEADLIGHT ASSYL	Not Necessary	501.37 FS	*- FS
18	1		*NUMBER PLATE WITH CASING	Cut	45.00 FS	*45.00 FS
19	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>3,087.16      1,933.38</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	150.00
2	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	500.00	450.00
3	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	2,100.00	1,300.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,700.00	1,040.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,480.00</b>	<b>2,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >