

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22006418/KQY3M4**Date:** 17/08/2022**REFERENCE**

Insured/Claimant: BIS MOTORING PTE LTD Policy No: MCF22A00000100
Date of Loss: 22/06/2022 Nature of Claim: OD Claim No: DMCF2200118H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK6945Y**
Make & Model: RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A) Engine No: K9KF649D059609
Reg. Date: 22/04/2019 (Man. Year: 2019) Chassis No: VF1RFA00062476756
Colour: Metallic Gold Odometer: 200155 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$78,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,906.03	14,498.44	4,407.59	23.31
Miscellaneous Items	87.00	0.00	87.00	100.00
Labour	3,370.00	1,040.00	2,330.00	69.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,363.03	15,538.44	6,824.59	30.52
Approved Total (Overridden) (S\$)		9,300.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	20,363.03	7,300.00	13,063.03	64.15
+ GST 7.00/7.00% (S\$)	1,425.41	511.00	914.41	64.15
Nett Amount (S\$)	21,788.44	7,811.00	13,977.44	64.15

INSPECTION

Date of Assignment: 05/07/2022 Present Location: Munich Autocare Pte Ltd (HQ)
Date Inspected: 06/07/2022 Inspected At: Munich Autocare Pte Ltd (HQ)
Estimated Period of Repair: 5.0 days 60 Jalan Lam Huat, #07-43
Singapore 737869

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2022)
Parts:	M1-MPV	RENAULT SCENIC IV 1.5 D L DCI SR EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK6945Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	651004703R	*FRONT BONNET (WCP)	Bent	1,348.00 F	*1,348.00 F
2	1	656016673R	*BONNET LOCK (WCP)	Repair	186.00 F	*- F
3	1	654000247R	*FRONT BONNET HINGE RH (WCP)	Repair	134.30 F	*- F
4	1	654013594R	*FRONT BONNET HINGE LH (WCP)	Distorted	134.30 F	*134.30 F
5	1	658408772R	*FRONT BONNET INSULATOR (WCP)	Serviceable	295.20 F	*- F
6	1	654704597R	*FRONT BONNET DAMPER LH (WCP)	Serviceable	112.20 F	*- F
7	1	654704597R	*FRONT BONNET DAMPER RH (WCP)	Serviceable	112.20 F	*- F
8	1	260101271R	*FRONT HEADLAMP RH (WCP)	Mtg Cracked	892.50 F	*892.50 F
9	1	260602165R	*FRONT HEADLAMP LH (WCP)	Mtg Cracked	892.50 F	*892.50 F
10	1	622907255R	*FRONT CENTRE BRACE BRACKET (WCP)	Distorted	132.90 F	*132.90 F
11	1	620223972R	*FRONT BUMPER (WCP)	Mtg Cracked	1,676.20 F	*1,461.70 F
12	1	625005785R	*FRONT SUPPORT PANEL (WCP)	Bent	1,214.30 F	*1,214.00 F
13	1	253A49995R	*FRONT PARKING SENSOR x4 (WCP)	Serviceable	2,228.80 F	*- F
14	1	2843896148R	*FRONT BLIND SPOT SENSOR RH x2 (WCP)	Serviceable	723.40 F	*- F
15	1	623821034R	*FRONT RADIATOR GRILLE BLACK (WCP)	Mtg Cracked	265.00 F	*265.00 F
16	1	623855072R	*FRONT RADIATOR GRILLE MOULDING (CHROME) (WCP)	Cracked	329.80 F	*329.80 F
17	1	622561964R	*FRONT RADIATOR GRILLE (WCP)	Cracked	473.80 F	*473.80 F
18	1	628905855R	*FRONT GRILLE EMBLEM (WCP)	Cracked	167.00 F	*167.00 F
19	1	620363937R	*FRONT RADIATOR TOP GARNISH (WCP)	Buckled	458.40 F	*458.40 F
20	1	752106346R	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	744.40 F	*744.40 F
21	1	620901789R	*FRONT BUMPER LOWER REINFORCEMENT GARNISH (WCP)	Cracked	239.10 F	*239.10 F
22	1	7711428130	*COOLANT 5L (WCP)	Necessary	24.20 F	*24.20 F
23	1	921004063R	*AIRCON CONDENSER (WCP)	Punctured	930.00 F	*930.00 F
24	1	144614EA1B	*ENGINE INNER COOLER (WCP)	Punctured	898.10 F	*898.10 F
25	1	214105169R	*RADIATOR (WCP)	Punctured	725.40 F	*725.40 F
26	1	214819674R	*RADIATOR FAN COWLING ASSY (WCP)	Cracked	937.20 F	*937.20 F
27	1	628109433R	*RADIATOR GRILLE INNER AIR DUCT (WCP)	Cracked	165.30 F	*165.30 F

Report was unsubmitted during this print-out.

8/17/22, 2:01 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1	215595656R	*RADIATOR INNER AIR DUCT (WCP)	Cracked	102.80 F	*102.80 F
29	1	215586371R	*INTERCOOLER AIR DUCT (WCP)	Cracked	46.60 F	*46.60 F
30	1	214F62853R	*FRONT LOWER AIR INTAKE FLAP GUIDE (WCP)	Cracked	597.40 F	*597.40 F
F=Franchise part.						
Sub Total (\$)					17,187.30	13,180.40
+ Margin on L,N Items 10.00/10.00% (\$)					1,718.73	1,318.04
Total Parts (\$)					18,906.03	14,498.44
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER SCREW (Serviceable)	42.00	0.00
2	1	FRONT NUMBER PLATE (Serviceable)	45.00	0.00
Sub Total (\$\$)			87.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE / WELADING REALIGN FROT BUMPER , BONNET, FRONT WINDS SUB FRAME, CHASSISD MEMBER FRONT ASSY LH/RH AND ALL NECESSARY ETC	New	1,000.00	500.00
2	TO REMOVE & REPLACE RADIATOR FAN , HOSE AND AIR COND CONDENSER HOSE , FAN INLUDING VECUUM AND TOP UP GAS	New	370.00	100.00
3	TO DIAGNOSTIC SETTING PASSENGER & DRIVER RESTRAINT SYSTEM AND RESETTNG OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00	0.00
4	TO CONDUCT 4 WHEEL ALIGMENT / TYRE BALANCING	New	120.00	0.00
5	TO RESPRAY FRONT ACCIDENT PORTION , BONNET , BUMPER CHASSIS MEMBERASSY RH/LH AND NECESSARY ETC	New	1,500.00	440.00
Gross Labour Cost (\$\$)			3,370.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >