

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006421/UQY3Q2**Date:** 22/11/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00144632101	
Claimant Vehicle No :	GBG627G	Insured Vehicle No :	YP4750L	
Date of Loss:	04/07/2022	Nature of Claim:	TP	Claim No: SNM22D204661/C02/THAMYL/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG627G		Engine No:	YD25415930A
Make & Model:	NISSAN NV350, 2.5 (A)		Chassis No:	JN1MC2E26Z0007947
Reg. Date:	29/05/2017 (Man. Year: 2016)		Odometer:	156023 km
Colour:	Black			
Engine Capacity:	2488 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	855.63	783.72	71.91	8.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	720.00	800.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,375.63	1,503.72	871.91	36.70
+ GST 7.00/7.00% (S\$)	166.29	105.26	61.03	36.70
Nett Amount (S\$)	2,541.92	1,608.98	932.94	36.70

INSPECTION

Date of Assignment:	18/11/2022	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977
Date Inspected:	18/07/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Nov 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG627G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Broken	391.50 FL	*391.50 FL
2	1		*FRONT GRILLE ASSEMBLY	Cracked	479.30 FL	*479.30 FL
3	1		*FRONT GRILLE EMBLEM	Not Necessary	79.90 FL	*- FL
4	1		*CORNER PANEL RH (NPA)	Not Necessary	0.00 FS	*- FS
5	1		*BONNET (NPA)	Not Necessary	0.00 FS	*- FS
6	1		*FRONT PANEL (NPA)	Repair	0.00 FS	*- FS
7	1		*FRONT BUMPER (NPA)	Repair	0.00 FS	*- FS
					Sub Total (\$\$)	950.70 870.80
					- List Item Discount on L Items 10.00/10.00% (\$\$)	95.07 87.08
					Total Parts (\$\$)	855.63 783.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	400.00
3	ANTI-RUST COATING	New	80.00	0.00
4	WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			1,520.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >