



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 329L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, FRONT BUMPER	TO REPAIR SEE LABOUR	516.00	-
1	GRILLE, RADIATOR, LOWER NO.1	SERVICEABLE	170.10	-
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	TO REPAIR SEE LABOUR	716.60	-
1	ABSORBER, FRONT BUMPER ENERGY	SERVICEABLE	79.60	-
1	RETAINER, REAR BUMPER SIDE, LH	SERVICEABLE	116.50	-
1	BRACKET, FRONT BUMPER SIDE, LH	SERVICEABLE	59.30	-
1	UNIT ASSY, HEADLAMP, LH	SERVICEABLE	2,637.60	-
1	LAMP ASSY, FOG, LH	SERVICEABLE	951.40	-
1	FENDER SUB-ASSY, FRONT LH	TO REPAIR SEE LABOUR	977.80	-
1	FRONT FENDER EMBLEM LH	NECESSARY	54.60	54.60
1	LINER, FRONT FENDER, LH	SERVICEABLE	202.50	-
	LESS 25% DISCOUNT		-1,620.50	-13.65
			4,861.50	40.95
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER CLIP (SN)	NOT NECESSARY	70.00	-
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	75.00	-
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	90.00	-
			235.00	-
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF COVER, FRONT BUMPER, REINFORCEMENT SUB-ASSY, FRONT BUMPER AND FENDER SUB-ASSY, FRONT LH.		1,600.00	200.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CS/AGI22006422/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	440.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			4,380.00	640.00
GRAND TOTAL			9,476.50	680.95

RECOMMENDED COST OF REPAIRS				680.95
------------------------------------	--	--	--	---------------

Report Ref No. CS/AGI22006422/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.