

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 110k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC893/E Yr Regn: 614 120Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi ROSA c.c. 4899Colour: white A/C: Insured / Std / NI / NASp. Reading: 6523 T/Radio: Insured / Std / NI / NAEng/No: BE 6415K30766

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim STD A/Rim orTyre Size: F: 205/85R16R: 205/85R16

B3 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmD.O.A. 9/7/22 D.O.I. 12/7/22 1630Survey held at NyduDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MU: 110kRebate: 14083NW: 90417

Date/Time, File Pass 1/1

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return 1/1

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

B + RB, 61

Photos

Others

TOTAL

Ryder

Auto Pte Ltd
LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To resurvey before/after third party survey
• To resurvey before/after confirmation
• Third party survey is on a "Without Prejudice" basis
• No cash payment(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921
Email: ryderautoworkshop@gmail.com
Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# PC8931E

Accident Date 4/7/2022

Location : tpe towards slc

Acknowledged by Repairer

Signature:

Date:

Model:

MITSUBISHI / ROSA BE64

6/4/2020

3P:

GBA8993C(CHINA
TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper	1,726.00		
2	2pcs	Rear bumper o/s & n/s retainer	312.40		
3	4pcs	Rear bumper centre bracket	284.60		
4	2pcs	Rear o/s & n/s bumper reflector	310.60		
5	1 pc	Rear n/s tail-gate	5,203.00		
6	1 pc	Rear tail-gate weatherstrip	420.00		
7	1 pc	Rear windscreen moulding	336.00		
8	1 pc	Rear o/s tail gate	5,344.00		
9	1 pc	Rear end panel			
10	1 pc	Rear windscreen moulding	316.80		
		Sub-Total:	14,253.40	0.00	0.00
			10%	0%	0%
		After Less %:	12828.06	0.00	0.00

DT
XNWSUCX
ncc
XSUC
Xr
XNWSUC
XNN
Xr
XNN
XNN
1809.50

	Labour	
1	To dismantle rear portion, straighten and welding.	1,000.00
2	To spray painting.	800.00
3	To remove and refit rear n/s windscreen.	140.00
4	To remove and refit rear o/s windscreen.	140.00
5	To remove and replace rear tail-gate.	150.00
6	To check wiring.	50.00
7	To re-seal anti-rust.	60.00
	Sub-Total:	2,340.00
	Total:	15168.06
	After Less 20%:	12134.45

700
XNW
XNW
XNW
30
30
3369.5

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

