



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 3677L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	BENT	762.60	762.60
1	REAR BOOT LID INNER TRIM	SERVICEABLE	164.20	-
1	REAR BOOT LID SYLPHY EMBLEM	NECESSARY	113.30	97.60
1	REAR BOOT LID NISSAN LOGO	NECESSARY	60.90	60.90
1	REAR BOOT LID OUTER CHROME MOULDING	CRACKED	219.40	219.40
1	REAR BOOT LID MECHANISM LOCK	DENTED	93.30	93.30
1	REAR BOOT WEATHERSTRIP	DISTORTED / DENTED	105.10	105.10
2	TAIL LAMP L/R @\$409.10	O/S MTG CRACKED	818.20	409.10
1	REAR BUMPER	BUCKLED	749.90	669.00
2	REAR BUMPER SIDE RETAINER L/R @\$43.80	O/S DISTORTED	87.60	43.80
1	REAR BUMPER INNER SPONGE	CRACKED	155.90	155.90
1	REAR END PANEL	TO REPAIR SEE LABOUR	520.60	-
1	REAR END PANEL TOP GARNISH	MTG CRACKED	117.10	117.10
	LESS 10% DISCOUNT		-396.81	-273.38
			<b>3,571.29</b>	<b>2,460.42</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
1	SET REAR END TOP GARNISH CLIPS (SN)	NECESSARY	35.00	35.00
1	SET REAR BOOT LID TRIM BOARD CLIPS (SN)	NOT NECESSARY	35.00	-
1	SET REVERSE SENSOR (SN)	DENTED	250.00	200.00
			<b>365.00</b>	<b>280.00</b>
<b><u>LABOUR</u></b>				
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.		80.00	20.00
	TO REMOVE & REPLACE UPHOLSTRY, TRIM GARNISHES TO FACILITATE REPAIRS.		100.00	50.00
	TO REMOVE, TRANSFER BOOT LID COMPONENTS.		80.00	50.00
	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	500.00

Report Ref No. CS/FCI22006429/Kqy3m4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		700.00	600.00
	TO REMOVE & RENEW REVERSE SENSOR.		80.00	50.00
	RUST PROOFING ON AFFECTED PORTIONS.		80.00	30.00
			1,920.00	1,300.00
<b>GRAND TOTAL</b>			<b>5,856.29</b>	<b>4,040.42</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/FCI22006429/Kqy3m4

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.