

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122006432/AVY3Q2**Date:** 22/11/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SY6108C**Insured Vehicle No :** SKR2797X

Date of Loss: 02/07/2022

Nature of Claim: TP

Claim No: CDMPG22001285

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SY6108C**

Make & Model: LEXUS RX, 300 LUXURY (A)

Engine No: 8AR4038872

Reg. Date: 30/09/2019 (Man. Year: 2019)

Chassis No: JTJBAMCA702072350

Colour: Red

Odometer: 92320 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R20

Rear Tyre Size: 235/55 R20

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,345.70	9,099.20	6,246.50	40.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,550.00	1,980.00	56.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,875.70	10,649.20	8,226.50	43.58
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	18,875.70	8,500.00	10,375.70	54.97

INSPECTION

Date of Assignment: 05/07/2022

Date Inspected: 05/07/2022 Inspected At:

YSK Auto Workshop (HQ)
1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
Parts:	M1-SUV	LEXUS RX 300 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SY6108C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	995.00 F	*995.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	163.80 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Distorted	361.40 F	*361.40 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	371.20 F	*- FL
6	1		*REAR BUMPER SPONGE	Cracked	266.90 F	*266.90 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	568.80 F	*568.80 FL
8	2		*REAR BUMPER EXHAUST CHROME	Cut	650.20 F	*650.20 FL
9	2		*REAR BUMPER LOWER BRACKET	Bent	70.20 F	*70.20 FL
10	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,416.40 F	*708.20 FL
11	4		*REVERSE SENSOR HOLDER	Necessary	100.00 F	*100.00 FL
12	1		*REAR END PANEL	Repair	926.30 F	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	321.50 F	*- FL
14	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
15	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
16	1		*TAILGATE	Dented	3,263.00 F	*2,689.00 FL
17	1		*TAILGATE LOCK	Not Necessary	1,006.40 F	*- FL
18	1		*TAILGATE WEATHERSTRIPE	Not Necessary	458.80 F	*- FL
19	1		*TAILGATE GLASS MOULDING	Necessary	245.90 F	*185.00 FL
20	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
21	1		*LEXUS WORDING	Necessary	85.90 F	*85.90 FL
22	1		*RX 300 WORDING	Necessary	92.50 F	*92.50 FL
23	1		*REAR EXHAUST PIPE	Bent	1,485.40 F	*1,245.00 FL
24	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.90 F	*- FL
25	1		*REAR EXHAUST PIPE GASKET	Necessary	35.50 F	*35.50 FL
26	1		*REAR EXHAUST HEAT SHIELD	Dented	369.80 F	*245.40 FL
27	1		*CENTRE EXHAUST PIPE	Bent	1,854.90 F	*1,689.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,345.70	10,098.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	998.80
Total Parts (\$)	15,345.70	9,099.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING	New	1,000.00	500.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE REAR VIDEO RECORDER	New	100.00	0.00
7	TO REMOVE UPHOLSTERY	New	150.00	40.00
8	TO SPRAY TUFF COAT	New	150.00	40.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE REAR AND CENTRE EXHAUST PIPE	New	300.00	160.00
Gross Labour Cost (S\$)			3,530.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >