

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22006433/ACY3Q2**Date:** 07/10/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SMM2883H **Insured Vehicle No :** GBG5842T
 Date of Loss: 03/07/2022 Nature of Claim: TP Claim No: CDMCG22001292

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM2883H**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B5569056
 Reg. Date: 25/06/2019 (Man. Year: 2019) Chassis No: RU11319019
 Colour: White Odometer: 29928 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,792.40	5,814.56	4,977.84	46.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,910.00	1,620.00	45.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,322.40	7,724.56	6,597.84	46.07
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	14,322.40	6,200.00	8,122.40	56.71

INSPECTION

Date of Assignment: 05/07/2022
 Date Inspected: 05/07/2022 Inspected At: YSK Auto Workshop (HQ)
 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2022)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMM2883H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	745.40 F	*745.40 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Necessary	64.80 F	*64.80 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	282.20 F	*- FL
7	2		*REAR BUMPER SIDE GARNISH	Not Necessary	390.00 F	*- FL
8	1		*REAR BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*780.00 FS
9	1		*REAR BUMPER LOWER COVER	Deformed	295.40 F	*295.40 FL
10	1		*REAR BUMPER LOWER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
11	1		*REAR END PANEL	Dented	585.10 F	*585.10 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 F	*98.40 FL
13	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
14	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
15	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	60.20 F	*- FL
16	1		*REAR END PANEL BUZZER	Not Necessary	85.20 F	*- FL
17	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
18	1		*TAILGATE	Dented	1,100.00 F	*1,100.00 FL
19	1		*TAILGATE LOCK	Damaged	182.50 F	*182.50 FL
20	1		*TAILGATE WEATHERSTRIPE	Cut	188.90 F	*188.90 FL
21	1		*TAILGATE OUTER GARNISH	Not Necessary	325.40 F	*- FL
22	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
23	1		*TAILGATE INNER TRIM BOARD	Cracked	285.60 F	*285.60 FL
24	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
25	2		*TAILGATE REFLECTOR	Cut	826.40 F	*826.40 FL
26	1		*TAILGATE GLASS MOULDING	Necessary	120.40 F	*120.40 FL
27	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*HONDA LOGO	Not Necessary	30.40 F	*- FL
29	1		*VEZEL EMBLEM	Necessary	45.90 F	*45.90 FL
30	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
31	1		*REAR FENDER INNER TRIM BOARD	O/S Cracked	610.40 F	*305.20 FL
32	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
33	2		*TAILLAMP	Cracked	949.20 F	*949.20 FL
34	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	306.60 F	*- FL
35	1		*TOOLS TRAY SPONGE	Not Necessary	285.40 F	*- FL
36	1		*REAR EXHAUST PIPE	Not Necessary	598.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,792.40	6,973.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,158.64
Total Parts (\$)	10,792.40	5,814.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	30.00
5	TO REMOVE REAR CAMERA	New	100.00	30.00
6	TO REMOVE REAR VIDEO RECORDER	New	100.00	30.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO SPRAY TUFF COAT	New	150.00	50.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE EXHAUST PIPE	New	150.00	0.00
			Gross Labour Cost (S\$)	1,910.00
				3,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >