



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FL 538G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRT WHEEL MUDGUARD (N)	BUCKLED	250.00	250.00
1	HEADLAMP (N)	CRACKED	200.00	200.00
1	HEADLAMP HOUSING (N)	CRACKED	350.00	350.00
1	REAR VIEW MIRROR RH (N)	DENTED	90.00	90.00
1	FRT HANDLE BRAKE LEVER RH (N)	DISTORTED	25.00	25.00
1	FRT FRAME RUBBER RH (N)	CUT	80.00	80.00
1	FOOTBOARD GARNISH RH (N)	SERVICEABLE	55.00	-
1	FRT FENDER SIGNAL LAMP RH (N)	CUT	25.00	25.00
1	REAR WHEEL COVER RH (N)	TO REPAIR SEE LABOUR	120.00	-
1	REAR WHEEL COVER INDICATOR LAMP RH (N)	SERVICEABLE	55.00	-
1	REAR HELMET BOX (N)	DENTED / CUT	90.00	90.00
	LESS 10% DISCOUNT		-	-111.00
			1,340.00	999.00
1	FRT NO PLATE (SN)	BENT	35.00	20.00
			35.00	20.00
<b>LABOUR</b>				
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.		30.00	15.00
	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR WHEEL COVER RH.		400.00	180.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		300.00	200.00
			730.00	395.00
<b>GRAND TOTAL</b>			<b>2,105.00</b>	<b>1,414.00</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,100.00</b>
---	--	--	-----------------

Report Ref No. CS/AGI22006434/Kvy3m4

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**