



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2204609

INV Date 26/07/2022

Reference CS3/EQI22000665/Vvy3e2-  
'

Code EQI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SJM 3180G  
Insured Veh. SKR 8335G  
Claim No. DM22HO00091/MT  
Policy No.  
Accident Date 13/01/2022  
Inspection Date 19/01/2022

| Description        | Total         |
|--------------------|---------------|
| Survey Report      | 150.00        |
| <b>Subtotal</b>    | <b>150.00</b> |
| <b>GST (7%)</b>    | <b>10.50</b>  |
| <b>Grand Total</b> | <b>160.50</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX SINGAPORE 069110

Ref: CS3/EQI22000665/Vvy3e2-1

Date: 26/07/2022

Code: EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | SKR 8335G      | <b>Veh. Inspected</b> | SJM 3180G  |
| <b>Policy No.</b>   |                | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | DM22HO00091/MT | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | LEE PEY SHY    | <b>Assign Date</b>    | 04/07/2022 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |                    |
|-------------------------|-------------------|---------------------|--------------------|
| <b>Make &amp; Model</b> | TOYOTA WISH       | <b>c.c</b>          | 1794               |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2008               |
| <b>Chassis No.</b>      | JTDER12W703001230 | <b>Colour</b>       | SILVER             |
| <b>Odometer</b>         | 449486 KM         | <b>Steering</b>     | IN ORDER           |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | STANDARD ALLOY RIM |
| <b>General</b>          | GOOD              |                     |                    |

### 3. Conditions of Tyres

|                       | Size       | Make      | Balance |
|-----------------------|------------|-----------|---------|
| <b>R/H Front Tyre</b> | 205/55 R16 | WEST LAKE | 5 mm    |
| <b>L/H Front Tyre</b> | 205/55 R16 | WEST LAKE | 5 mm    |
| <b>R/H Rear Tyre</b>  | 205/55 R16 | WEST LAKE | 5 mm    |
| <b>L/H Rear Tyre</b>  | 205/55 R16 | WEST LAKE | 5 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |                           |                        |            |
|-----------------------|---------------------------|------------------------|------------|
| <b>Accident Date</b>  | 13/01/2022                | <b>Inspection Date</b> | 19/01/2022 |
| <b>Survey held at</b> | 8 KAKI BUKIT AVE 4 #04-20 |                        |            |
| <b>Repairer</b>       | A-TEC AUTOMOTIVE PTE LTD  |                        |            |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 3180G

| Qty                                | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |                      |                           |                   |
| 1                                  | REAR BUMPER ASSY  | WARPED / DENTED      | 1,200.00                  | 590.00            |
| 1                                  | SET REAR BUMPER RETAINER  | WARPED / NECESSARY   | 350.00                    | 148.00            |
| 1                                  | SET REAR BUMPER BRACKET   | NOT NECESSARY        | 380.00                    | -                 |
| 1                                  | SET REAR BUMPER REFLECTOR   | NOT NECESSARY        | 475.00                    | -                 |
| 1                                  | REAR BUMPER WEATHERSTRIP  | WARPED / NECESSARY   | 385.00                    | 274.00            |
| 1                                  | REAR TAILGATE ASSY  | TO REPAIR SEE LABOUR | 1,350.00                  | -                 |
| 1                                  | REAR TAILGATE LOCK CATCH  | BENT                 | 320.00                    | 320.00            |
| 1                                  | REAR TAILGATE INNER GARNISH   | NOT NECESSARY        | 420.00                    | -                 |
| 1                                  | REAR TAILGATE OUTER GARNISH   | NOT NECESSARY        | 480.00                    | -                 |
| 1                                  | REAR TAILGATE "TOYOTA" LOGO   | REUSE                | 280.00                    | -                 |
| 1                                  | REAR TAILLAMP LH  | CRACKED              | 1,100.00                  | 589.00            |
| 1                                  | REAR TAILLAMP RH  | NOT NECESSARY        | 1,100.00                  | -                 |
| 1                                  | REAR EXHAUST PIPE MUFFLER   | NOT NECESSARY        | 685.50                    | -                 |
| 1                                  | REAR END PANEL ASSY   | TO REPAIR SEE LABOUR | 720.00                    | -                 |
|                                    | LESS 25% DISCOUNT   |                      | -2,311.38                 | -480.25           |
|                                    |   |                      | 6,934.12                  | 1,440.75          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |                      |                           |                   |
| 1                                  | SET REAR BUMPER CLIPS (SN)  | NECESSARY            | 100.00                    | 30.00             |
| 1                                  | SET REAR BUMPER REVERSE SENSOR (SN)   | MALFUNCTION          | 650.00                    | 200.00            |
| 1                                  | SET REAR END PANEL SEALANT (SN)   | NOT NECESSARY        | 120.00                    | -                 |
|                                    |   |                      | 870.00                    | 230.00            |
| <b><u>LABOUR</u></b>               |   |                      |                           |                   |
|                                    | TO CUT, WELD, STRAIGHTEN AFFECTED AREAS AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE ASSY AND REAR END PANEL ASSY. |                      | 2,400.00                  | 500.00            |
|                                    | TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS. JOB ALLOWANCE.  |                      | 2,400.00                  | 600.00            |
|                                    | TO CHECK REAR LIGHTING AND WIRING.  |                      | 280.00                    | 30.00             |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|---------------------------|-------------------|
|     | TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS.                          | NOT NECESSARY | 300.00                    | -                 |
|     | TO REMOVE AND INSTALL REAR BUMPER ASSY.                                     | NOT NECESSARY | 280.00                    | -                 |
|     | TO REMOVE AND INSTALL GARNISH AND TRIM TO FACILITATE THE REPAIR.            |               | 280.00                    | 60.00             |
|     | TO REMOVE AND INSTALL TAILLAMPS.  | NOT NECESSARY | 280.00                    | -                 |
|     | TO REMOVE AND INSTALL EXHAUST MUFFLER PIPE.                                 | NOT NECESSARY | 280.00                    | -                 |
|     | TO REMOVE AND INSTALL TAILGATE ASSY.  | NOT NECESSARY | 280.00                    | -                 |
|     | TO REMOVE AND INSTALL LOCK MECHANISM.                                       | NOT NECESSARY | 280.00                    | -                 |
|     | TO CONDUCT CENTRAL LOCK SYSTEM.   | NOT NECESSARY | 300.00                    | -                 |
|     | TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.                           |               | 280.00                    | 50.00             |
|     | TO CONDUCT CHASSIS ALIGNMENT.   | NOT NECESSARY | 300.00                    | -                 |
|     |   |               | 7,940.00                  | 1,240.00          |
|     | <b>GRAND TOTAL</b>  |               | <b>15,744.12</b>          | <b>2,910.75</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |               |                           | <b>2,300.00</b>   |

Report Ref No. CS3/EQI22000665/Vvy3e2-1

**THEVAN THOMAS KARTHIKESAVAN**

Asst. Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.