

Navigation icons: back, forward, search, refresh, zoom (100%), print, find | Next



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6256 3561 FAX: 6256 4315  
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

<b>Affiliated to Federation Internationale Des Experts En Automobile</b>		CS3/EQI22000665/Vvy3-1
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: <del>GG/EQI22000665/Vvy3</del> Date: <del>19/01/2022</del> 04/07/2022 Code: EQI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>		
<b>Insured Veh.</b> SKR 8335G	<b>Veh. Inspected</b> SJM 3180G	
<b>Policy No.</b>	<b>Coverage (\$)</b> 0.00	
<b>Claim No.</b> DM22HO00091/MT	<b>Excess (\$)</b> 0.00	
<b>Assign From</b> <del>MELODY TEOH</del> LEE PEY SHY	<b>Assign Date</b> <del>19/01/2022</del> 04/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>		
<b>Make &amp; Model</b>	<b>c.c</b> 0	
<b>Engine No.</b> HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>	<b>Colour</b>	
<b>Odometer</b> -	<b>Steering</b>	
<b>Brakes</b>	<b>Modification</b>	
<b>General</b>		
<b>3. Conditions of Tyres</b>		
	<b>Size</b>	<b>Make</b>
<b>R/H Front Tyre</b>		<b>Balance</b> mm
<b>L/H Front Tyre</b>		mm
<b>R/H Rear Tyre</b>		mm
<b>L/H Rear Tyre</b>		mm
<b>4. Description of Damages</b>		
<b>5. General Information</b>		
<b>Accident Date</b> 13/01/2022	<b>Inspection Date</b> 19/01/2022	
<b>Survey held at</b> #04-20		
<b>Repairer</b> A-TEC AUTOMOTIVE PTE LTD		
<b>5a. Remarks</b>		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		