

J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

VEHICLE INSPECTION REPORT

To: RENTY PTE LTD Date : 23 March 2022
C/o: A-Tec Automotive Pte Ltd Our ref : ATEC/03/0008/JM
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Accident Date : 13 January 2022 Type of Survey : Third party
Inspection Date : 17 January 2022
Repairer Name : A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

PARTICULARS OF VEHICLE

Registration No : SJM 3180 M Year / Capacity : 2008 / 1794 cc
Make / Model : Toyota / Wish Colour : Silver
Chassis No : JTDER12W703001230 Mileage : 449,486 km
Engine No : 1ZZ3186660

CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside	: Firenza	205/55/ R16	80%
Front Offside	: Firenza	205/55/ R16	80%
Rear Nearside	: Westlake	205/55/ R16	80%
Rear Offside	: Westlake	205/55/ R16	80%

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear bumper portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 58 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

J&M CONSULTANCY PTE LTD

Vehicle Registration No: SJM 3180 G

Our Ref No: ATEC/03/0008/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about **14 (Fourteen)** working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear bumper assy	Warped/Dented ✓	\$ 1,200.00	\$ 1,200.00 ⁵⁹⁰
1	Rear bumper retainer (1 set)	Warped/Necessary ✓	\$ 350.00	\$ 350.00 ¹⁴⁸
1	Rear bumper bracket (1 set)	Warped/Necessary	\$ 380.00	\$ 380.00 X NN
1	Rear bumper reflector (1 set)	Cracked	\$ 475.00	\$ 475.00 X NN
1	Rear bumper weatherstrip	Warped/Necessary ✓	\$ 385.00	\$ 385.00 ²⁷⁴
1	Rear tailgate assy	Warped	\$ 1,350.00	\$ 1,350.00 X R
1	Rear tailgate lock catch	Bent ✓	\$ 320.00	\$ 320.00
1	Rear tailgate inner garnish	Warped	\$ 420.00	\$ 420.00 X NN
1	Rear tailgate outer garnish	Warped	\$ 480.00	\$ 420.00 X NN
1	Rear tailgate "Toyota" logo	Reuse	\$ 280.00	\$ -
1	Rear taillamp LH	Cracked ✓	\$ 1,100.00	\$ 1,100.00 ⁵⁸⁹
1	Rear taillamp RH	Cracked	\$ 1,100.00	\$ 1,100.00 X NN
1	Rear exhaust pipe muffler	Bent	\$ 685.50	\$ 685.00 X NN
1	Rear end panel assy	Warped	\$ 720.00	\$ 720.00 X R
			Total	\$ 9,245.50 \$ 8,905.00
			Less 25%	\$ 2,311.38 \$ 2,226.25
			\$ 6,934.13	\$ 6,678.75

SPECIAL NETT ITEMS

1	Rear bumper clips (1 set)	Necessary	\$ 100.00	\$ 100.00 ³⁰
1	Rear bumper reverse sensor (1 set)	Malfunction	\$ 650.00	\$ 650.00 ²⁰⁰
1	Rear end panel sealant (1 set)	Necessary	\$ 120.00	\$ 120.00 X NN
Total parts			\$ 7,804.13	\$ 7,548.75

J&M CONSULTANCY PTE LTD

Vehicle Registration No: SJM 3180 G

Our Ref No: ATEC/03/0008/JM

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

J&M Consultancy Pte Ltd



Joel Liew Jian Xiang
Automotive Appraiser

