

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006438/AQCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant:	PANKAJ PORWAL	Policy No:	1800095031-03	
Date of Loss:	29/06/2022	Nature of Claim:	OD	Claim No: 7027114912SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD6285E		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK066847
Reg. Date:	28/08/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF4XJA216426
Colour:	Blue	Odometer:	43909 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,576.00	3,703.84	3,872.16	51.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,242.00	1,522.00	1,720.00	53.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,818.00	5,225.84	5,592.16	51.69
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	9,718.00	4,125.84	5,592.16	57.54
+ GST 7.00/7.00% (S\$)	680.26	288.81	391.45	57.54
Nett Amount (S\$)	10,398.26	4,414.65	5,983.61	57.54

INSPECTION

Date of Assignment:	06/07/2022	
Date Inspected:	05/07/2022	Inspected At: Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	3,431.00 FS	*2,744.80 FS
2	1		*REAR DOOR OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*REAR DOOR SEALING STRIP	Necessary	19.00 FS	*14.64 FS
7	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	943.00 FS	*- FS
8	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
9	1		*REAR DOOR HINGE HALF UPPER PART - LH UPPER (NPA)	Not Necessary	0.00 FS	*- FS
10	1		*REAR DOOR HINGE HALVES - LH LOWER	Not Necessary	50.00 FS	*- FS
11	1		*REAR DOOR HINGE HALF LOWER PART - LH UPPER (NPA)	Not Necessary	0.00 FS	*- FS
12	1		*REAR DOOR HINGE HALVES - LH LOWER (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*REAR DOOR WINDOW GUIDE - LH	Not Necessary	501.00 FS	*- FS
14	1		*REAR DOOR WINDOW GUIDE TRIM STRIP - LH	Not Necessary	265.00 FS	*- FS
15	1		*C-PILLAR TRIM - LH	Deformed	159.00 FS	*127.20 FS
16	1		*B-PILLAR TRIM - LH	Not Necessary	167.00 FS	*- FS
17	1		*REAR DOOR WINDOW SLOT SEAL TRIM STRIP - LH	Not Necessary	410.00 FS	*- FS
18	1		*SUNDRIES	Necessary	350.00 FS	*7.20 FS
19	1		*REAR DOOR WINDOWO TRIM - LH UPPER (Supplementary)	Cut	155.00 FS	*123.60 FS
20	1		*REAR DOOR LOCK - LH (Supplementary)	Damaged	630.00 FS	*503.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,576.00	3,703.84
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND RENEW LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
2	TO RESPRAY LHS REAR DOOR AND DOOR HANDLE	New	1,500.00	550.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
4	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
Gross Labour Cost (\$)			3,242.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >