

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006442/APA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210050871
Claimant Vehicle No :	GBF6265H	Insured Vehicle No :	SLF7788R
Date of Loss:	29/06/2022	Nature of Claim:	TP
		Claim No:	2491025688SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6265H		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2668973
Reg. Date:	06/01/2017 (Man. Year: 2016)	Chassis No:	JTFAT35Y80K207243
Colour:	White	Odometer:	191541 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,624.92	7,502.86	13,122.06	63.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,980.00	1,410.00	32.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,014.92	10,482.86	14,532.06	58.09
Approved Total (Overridden) (S\$)		8,100.00		
(S\$)	25,014.92	8,100.00	16,914.92	67.62
+ GST 8.00/8.00% (S\$)	2,001.19	648.00	1,353.19	67.62
Nett Amount (S\$)	27,016.11	8,748.00	18,268.11	67.62
+ Loss of Use (10.0 x S\$90.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,655.45		
Global Sum Settlement (S\$)		9,650.00		

INSPECTION

Date of Assignment:	04/07/2022	Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit Singapore 415875
Date Inspected:	04/07/2022 Inspected At:	
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	681.20 F	*681.20 FL
2	1		*FRONT BUMPER UPPER GARNISH	Not Necessary	422.30 F	*- FL
3	1		*FRONT GRILLE	Cracked	387.72 F	*387.72 FL
4	4		*FRONT GRILLE CLIPS	Necessary	51.60 F	*20.00 FL
5	1		*FRONT WIPER PANEL (CENTER)	Dented	752.10 F	*429.00 FL
6	1		*FRONT WATER TANK	Not Necessary	285.00 F	*- FL
7	2		*FRONT AIR COND COWLING	Not Necessary	916.60 F	*- FL
8	1		*FRONT WINDSCREEN MOULDING	Not Necessary	211.00 F	*- FL
9	1		*FRONT WINDSCREEN RUBBER	Necessary	387.20 F	*387.20 FL
10	1		*FRONT WINDSCREEN ERP STICKER	Necessary	30.00 F	*30.00 FL
11	1		*FRONT PANEL	Dented	1,150.00 F	*1,150.00 FL
12	1		*FRONT PANEL TOP COVER (CENTER)	Not Necessary	352.00 F	*- FL
13	1		*FRONT PANEL EMBLE LOGO	Necessary	83.70 F	*83.70 FL
14	2		*FRONT SIDE PANEL	Not Necessary	450.00 F	*- FL
15	1		*FRONT DYNA LOGO	Necessary	50.00 F	*50.00 FL
16	2		*FRONT HEADLAMP	Cracked	2,050.20 F	*1,296.00 FL
17	1		*REAR TAILGATE	Dented	2,500.00 F	*1,582.00 FL
18	1		*REAR TAILGATE TOP ALUMINIUM LID	Not Necessary	850.00 F	*- FL
19	1		*REAR TAILGATE END PANEL	Repair	858.00 F	*- FL
20	1		*REAR TAILGATE R/H 70KM/H LOGO	Necessary	25.00 FS	*15.00 FS
21	1		*REAR TAILGATE L/H 6PAX LOGO	Necessary	25.00 FS	*15.00 FS
22	1		*REAR TAILGATE BODY LOGO	Necessary	450.00 FS	*250.00 FS
23	2		*REAR TAILGATE R/H SIDE HINGE	Not Necessary	300.00 F	*- FL
24	2		*REAR TAILGATE L/H SIDE HINGE	Not Necessary	300.00 F	*- FL
25	1		*REAR TAILGATE CENTER BAR	Not Necessary	550.00 F	*- FL
26	1		*TAILGATE CENTER BAR TOP & LOWER LOCK	N/S Damaged	500.00 F	*250.00 FL
27	1		*REAR TAILGATE SIDE BRACKET	N/S Bent	600.00 F	*200.00 FL
28	1		*REAR TAILGATE LOCK HANDLE	Not Necessary	350.00 F	*- FL
29	1		*REAR TAILGATE LOWER CROSSMEMBER	Repair	580.00 F	*- FL
30	1		*REAR TAIL LAMP	N/S Cracked	700.00 F	*245.00 FL
31	1		*REAR NUMBER PLATE	Bent	50.00 F	*50.00 FL
32	1		*REAR NUMBER PLATE LAMP	Not Necessary	58.20 F	*- FL
33	1		*REAR STEP PANEL	Bent	350.00 FS	*180.00 FS
34	1		*REAR SPARE TIRE LOCK	Not Necessary	456.10 F	*- FL
35	1		*REAR SPARE TIRE	Not Necessary	280.00 F	*- FL
36	1		*AIR CON BLOWER	Cracked	1,193.00 F	*1,193.00 FL
37	1		*AIR CON EVAPORATOR	Cracked	1,089.00 F	*1,089.00 FL
38	1		*REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,624.92	9,783.82
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	2,280.96
Total Parts (S\$)	20,624.92	7,502.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX FRONT WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIX CUSHION	New	150.00	0.00
4	TO REMOVE & REFIX AIRCON COWLING & TOP UP GAS	New	200.00	120.00
5	TO CHECK WHEEL ALIGNMENT COMPUTER	New	120.00	0.00
6	TO CHECK WIRING SYSTEM	New	80.00	60.00
7	TUFF KOTE	New	120.00	60.00
8	PANEL BEATING	New	1,500.00	1,300.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
10	TO REMOVE DASHBOARD	New	350.00	220.00
11	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			4,390.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >