

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22006448/TCY3M4**Date:** 20/01/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR004648		
Claimant Vehicle No :	SHA8182E	Insured Vehicle No :	SLR3607T		
Date of Loss:	02/07/2022	Nature of Claim:	TP	Claim No:	M2203526

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8182E		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F55565
Reg. Date:	05/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU303089611
Colour:	Yellow	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,724.19	9,721.09	4,003.10	29.17
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,580.00	1,670.00	910.00	35.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,315.19	11,402.09	4,913.10	30.11
+ GST 7.00/7.00% (S\$)	1,142.06	798.15	343.91	30.11
Nett Amount (S\$)	17,457.25	12,200.24	5,257.01	30.11

INSPECTION

Date of Assignment:	06/07/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/07/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$11,402.08

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8182E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,117.93 FL	*1,117.93 FL
2	1		*BONNET HINGE LH	Bent	87.70 FL	*87.70 FL
3	1		*BONNET HINGE RH	Bent	87.70 FL	*87.70 FL
4	1		*BONNET LOCK	Not Necessary	132.60 FL	*- FL
5	1		*FRT FENDER LH	Bent	1,111.93 FL	*1,111.93 FL
6	1		*FRT FENDER SIDE BRACKET LH	Not Necessary	77.00 FL	*- FL
7	1		*HEADLAMP ASSY LH	Cracked	2,637.60 FL	*2,637.60 FL
8	1		*HEADLAMP ASSY RH	Not Necessary	2,637.60 FL	*- FL
9	1		*HEADLAMP PANEL UPPER	Bent	364.98 FL	*364.98 FL
10	1		*HEADLAMP PANEL LH	Bent	240.10 FL	*240.10 FL
11	1		*FRT BUMPER ASSY	Deformed	586.18 FL	*586.18 FL
12	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
13	1		*RADIATOR GRILLE	Cracked	438.00 FL	*438.00 FL
14	1		*FRT BUMPER LOWER GRILLE	Deformed	198.18 FL	*198.18 FL
15	1		*FRT BUMPER TOW COVER LH	Missing	28.38 FL	*28.38 FL
16	1		*FRT BUMPER TOW COVER RH	Missing	28.38 FL	*28.38 FL
17	1		*FRT BUMPER BEAM	Bent	812.89 FL	*812.89 FL
18	1		*FRT BUMPER BEAM STAY BRACKET LH	Not Necessary	138.00 FL	*- FL
19	1		*FRT BUMPER BEAM STAY BRACKET RH	Not Necessary	138.00 FL	*- FL
20	1		*BONNET EMBLEM	Necessary	198.18 FL	*198.18 FL
21	1		*RADIATOR ASSY	Bent	1,841.80 FL	*1,841.80 FL
22	1		*RADIATOR FAN GRILLE	Cracked	632.40 FL	*632.40 FL
23	1		*RADIATOR FAN MOTOR	Not Necessary	661.30 FL	*- FL
24	1		*CONDENSOR	Bent	2,924.20 FL	*1,374.02 FL
25	1		*FRT NUMBER PLATE	Bent	50.00 F	*50.00 F
26	1		*FRT NUMBER PLATE GARNISH	Deformed	99.00 FL	*99.00 FL
27	1		*FRT FENDER EMBLEM LH	Necessary	86.50 FL	*86.50 FL
28	1		*FRT BUMPER SPONGE	Cracked	78.80 FL	*78.80 FL
29	1		*FRT BUMPER FOG LAMP LH	Not Necessary	85.10 FL	*- FL
30	1		*SUPPORT FRONT BUMPER SIDE	Cracked	-	*82.30 FL
Supplementary #1						
31	1		*BATTERY	Deformed	220.00 F	*220.00 F
32	1		*CASE SUB - AIR CLEANER	Cracked	446.50 FL	*446.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	18,208.93	12,871.45
- List Item Discount on L Items 25.00/25.00% (\$)	4,484.74	3,150.36
Total Parts (\$)	13,724.19	9,721.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAYPAINT	New	900.00	750.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	RENEW / REFIX AIR CON AND REFILL GAS	New	120.00	100.00
6	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			2,580.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >