

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006449/UQCM4**Date:** 20/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00013592101

Claimant Vehicle No : SMC36C **Insured Vehicle No :** SKA8881K

Date of Loss: 04/07/2022 Nature of Claim: TP Claim No: SNM22D204663/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC36C**

Make & Model: HONDA FIT, 1.5 HYBRID (A) Engine No: LEB1450551

Reg. Date: 26/08/2019 (Man. Year: 2018) Chassis No: GP51341572

Colour: Grey Odometer: 119155 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,922.14	3,177.68	744.46	18.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	2,140.00	950.00	30.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,012.14	5,317.68	1,694.46	24.16
Approved Total (Overridden) (\$\$)		4,250.00		
Nett Amount (\$\$)	7,012.14	4,250.00	2,762.14	39.39

INSPECTION

Date of Assignment: 05/07/2022

Date Inspected: 06/07/2022 Inspected At: Sin Hwee Motor Pte Ltd (HQ)
Blk 3023A, Ubi Road 1, #01-59
Singapore 408717

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2022)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC36C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Badly Dented	947.54 FL	*854.20 FL
2	1		*BOOTLID CHROME	Not Necessary	309.44 FL	*- FL
3	1		*BOOTLID INNER LOCK	Bent	198.41 FL	*198.41 FL
4	1		*BOOTLID INNER TRIM	Serviceable	85.88 FL	*- FL
5	2		*WINDSCREEN SEAL	Necessary	191.20 FL	*191.20 FL
6	1		*FIT LOGO	Necessary	48.55 FL	*48.55 FL
7	1		*END PANEL	Dented	461.87 FL	*345.20 FL
8	1		*END PANEL TOP GARNISH	Twisted	174.77 FL	*174.77 FL
9	1		*WEATHER STRIP	Twisted	95.88 FL	*95.88 FL
10	1		*TAILLAMP L/H	Cracked	425.00 FL	*365.50 FL
11	1		*TAILLAMP R/H	Cracked	425.00 FL	*365.50 FL
12	1		*REAR BUMPER	Dented	592.77 FL	*592.77 FL
13	1		*REAR BUMPER CENTER GARNISH	Cut	85.88 FL	*85.88 FL
14	2		*SIDE RETAINER	Necessary	51.74 FL	*51.74 FL
15	1		*LOCK SENSOR	Cracked	165.00 FL	*165.00 FL
16	1		*REAR NUMBER PLATE	Scratched	90.00 FS	*80.00 FS
17	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
18	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,773.93	3,884.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	851.79	706.92
Total Parts (\$\$)	3,922.14	3,177.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	120.00
2	TO DISMOUNT AND MOUNT INNER TRIMS, BOARD AND FITTINGS TO FACILITATE REPAIR WORK	New	120.00	80.00
3	TO TRANSFER BOOTLID MECHANISM AND FITTINGS TO NEW BOOTLID	New	150.00	60.00
4	TO REPLACE END PANEL INCLUDE KNOCKING, CUTTING AND WELDING TO REPLACE, INSTALL AND ALIGN ABOVE ITEMS TO SYMMETRICAL SPEC	New	950.00	800.00
5	TO SPRAY PAINT REAR BUMPER, REAR BOOTLID, END PANEL AND FLOORBOARD PANEL	New	1,200.00	950.00
6	TO SUPPLY FITTING AND INSTALL REVERSE CAMERA	New	180.00	0.00
7	TO SUPPLY FITTINGS AND INSTALL REVERSE SENSOR	New	80.00	50.00
8	TO CARRY OUT WIRE CHECKING	New	80.00	20.00
9	TO SUPPLY AND TUFF KOTE	New	150.00	60.00
Gross Labour Cost (\$\$)			3,090.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >