

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006456/APA3Q2**Date:** 02/08/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100478995
Claimant Vehicle No :	SMT9578G	Insured Vehicle No :	SFQ2646M
Date of Loss:	03/07/2022	Nature of Claim:	TP
		Claim No:	4628206877SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9578G	Engine No:	CZD736206
Make & Model:	SKODA KODIAQ, 1.4 (A)	Chassis No:	TMBKC9NS7K8062594
Reg. Date:	16/09/2019 (Man. Year: 2019)	Odometer:	56849 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,028.70	1,139.02	7,889.68	87.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	810.00	1,090.00	57.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,928.70	1,949.02	8,979.68	82.17
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	10,928.70	1,500.00	9,428.70	86.27
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
Nett Liability (S\$)		1,620.00		

INSPECTION

Date of Assignment:	04/07/2022		
Date Inspected:	04/07/2022	Inspected At:	CERAMIC WORKS LLP 13 KAKI BUKIT ROAD 4 #01-29 BARTLEY BIZ CENTRE SINGAPORE 417807
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER ARC GARNISH	Cut	198.40 F	*198.40 FL
2	1		*FRONT LH FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
3	1		*FRONT LH DOOR	Repair	2,897.00 F	*- FL
4	1		*FRONT LH DOOR WEATHERSTRIPE	Not Necessary	214.90 F	*- FL
5	1		*FRONT LH DOOR WING MIRROR	Not Necessary	1,045.10 F	*- FL
6	1		*FRONT LH DOOR WING MIRROR COVER	Repair	125.90 F	*- FL
7	1		*REAR LH DOOR	Repair	2,818.00 F	*- FL
8	1		*REAR LH FENDER ARC GARNISH	Cut	189.40 F	*189.40 FL
9	1		*REAR LH FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
10	1		*REAR LH WHEEL RIM	Cut	1,500.00 FS	*750.00 FS
					Sub Total (S\$)	9,028.70 1,177.80
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 38.78
					Total Parts (S\$)	9,028.70 1,139.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	200.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
5	TO TRANSFER REAR DOOR FITTINGS	New	150.00	0.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			1,900.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >