

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22006466/KCE2

Date: 29/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962161		
Claimant Vehicle No :	SDE4331U	Insured Vehicle No :	SLV1517L		
Date of Loss:	30/06/2022	Nature of Claim:	TP	Claim No:	278077

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDE4331U	Engine No:	1872613
Make & Model:	DAIHATSU MATERIA, 1.5 (A)	Chassis No:	JDAM402S001006247
Reg. Date:	26/12/2007 (Man. Year: 2007)	Odometer:	273103 km
Colour:	Metallic Green		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Habilead 2 mm	Rear Left Side:	Habilead 2 mm
Front Right Side:	Habilead 2 mm	Rear Right Side:	Habilead 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,358.71	1,452.34	906.37	38.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	720.00	760.00	51.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,838.71	2,172.34	1,666.37	43.41
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,838.71	1,600.00	2,238.71	58.32
+ GST 7.00/7.00% (S\$)	268.71	112.00	156.71	58.32
Nett Amount (S\$)	4,107.42	1,712.00	2,395.42	58.32

INSPECTION

Date of Assignment:	06/07/2022	
Date Inspected:	02/08/2022	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2022)
Parts:	144	DAIHATSU MATERIA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDE4331U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	780.00 FN	*780.00 FN
2	1		*REAR BUMPER SIDE RETAINER RH	Distorted	55.00 FN	*55.00 FN
3	1		*REAR BUMPER BRACKET RH	Repair	75.50 FN	*- FN
4	1		*REAR LAMP RH	Mtg Cracked	324.00 FN	*324.00 FN
5	1		*REAR FENDER RH	Repair	636.00 FN	*- FN
6	1		*REAR FENDER LINER RH	Cracked	161.40 FN	*161.40 FN
7	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
8	1		*SET REAR FENDER LINER CLIPS	Necessary	35.00 FS	*35.00 FS
9	1		*REAR SPORT RIM RH	Dented	450.00 FS	*250.00 FS
					Sub Total (S\$)	2,561.90 1,650.40
					- Nett Item Discount on N Items 10.00/15.00% (S\$)	203.19 198.06
					Total Parts (S\$)	2,358.71 1,452.34

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE & REPLACE UPHOLSTRY, CUSHION SEAT & TRIM GARNISHES	New	100.00	0.00
3	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	500.00	250.00
4	PUTTY AND SPRAY PAINTING ON AFFECTED PORTIONS	New	600.00	400.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,480.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >