



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EZY-1 LEASING PTE LTD
55 SERANGOON NORTH AVE 4 #08-07 S9
SINGAPORE 555859

Contact : 87780300 94496542

TPAXA.
Ceilia.

TAX INVOICE

Repair Code : CLM17279
Date in : 05/07/2022
Vehicle Num. : GBL1468R
Model : TOYOTA HIACE DX 2.8 AUTO
Chassis/Eng# : GDH2012016873/1GD8678388

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehnd</i>	1	573.60	✓ 573.60
FRONT BUMPER FOGLAMP GARNISH LH <i>could</i>	1	59.80	✓ 59.80
FRONT BUMPER SIDE RETAINER L/R <i>LH cranked</i>	2	151.80	151.80 303.60
FRONT LH DOOR <i>Dented</i>	1	1999.70	1655 ✓ 1,999.70
FRONT LH DOOR HINGE (LOWER) <i>Not new</i>	1	116.90	✗ 116.90
FRONT LH DOOR WEATHER STRIP <i>Not new</i>	1	244.20	✗ 244.20
FRONT LH DOOR WEATHER STRIP (ARCH) <i>OK</i>	1	53.90	✓ 53.90
FRONT LH DOOR WIRE HARNESS COVER <i>Not new</i>	1	125.00	✗ 125.00
FRONT LH HEADLAMP <i>could</i>	1	2739.60	✓ 2,739.60
FRONT LH KNUCLE ARM <i>Not new</i>	1	740.50	✗ 740.50
FRONT LH KNUCLE ARM BEARING <i>Dented</i>	1	388.90	✓ 388.90
FRONT LH LOWER ARM	1	671.20	✗ 671.20
FRONT LH SHOCK ABSORBER <i>Not new</i>	1	134.70	✗ 134.70
FRONT LH STABILIZER LINK <i>Not new</i>	1	226.50	✗ 226.50
FRONT LH STEP GARNISH <i>could</i>	1	171.90	✓ 171.90
FRONT LH TIE ROD END <i>Not new</i>	1	179.30	✗ 179.30
FRONT LH WHEEL CAP <i>OK</i>	1	179.00	✓ 179.00
FRONT LH WHEEL RIM <i>Not new</i>	1	400.00	✗ 400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EZY-1 LEASING PTE LTD
55 SERANGOON NORTH AVE 4 #08-07 S9
SINGAPORE 555859

Contact : 87780300 94496542

TAX INVOICE

Repair Code : CLM17279

Date in : 05/07/2022

Vehicle Num. : GBL1468R

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2012016873/1GD8678388

	Subtotal before discount	5973.50	9,308.30
Percentage discount 25%		4480.12	2,327.08
	Sub-total 1		6,981.23
FRONT BUMPER CLIPS - SET <i>Nu</i>	1	80.00	30 80.00
FRONT LH DOOR COMPANY STICKER <i>Nu</i>	1	25.00	✓ 25.00
FRONT LH HEADLAMP CLIPS - SET <i>Nu</i>	1	25.00	10. 25.00
FRONT LH STEP GARNISH CLIPS - SET <i>Nu</i>	1	20.00	85 ✓ 20.00
FRONT LH TYRE <i>Nu Nu</i>	1	350.00	X 350.00
	Subtotal before discount		500.00
Percentage discount 0%			0.00
	Sub-total 2		500.00
	Parts-total		7,481.23

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

30 80.00
1450 60. 80.00
8w 1,200.00
500 800.00
60 100.00

Labour Total

2,260.00

Parts & Labour Total

9,741.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

*** This is a computer-generated document which requires no signature.***

page 2

total: 6015.12
L/S: 4.8K ✓

Adrian King
A/S 06/07/22
05 Days.